

AD-A069 943



















NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/2
NATIONAL DAM SAFETY PROGRAM. LAKE INEZ DAM (NJ-00228); PASSAIC --ETC(U)
MAY 79 R J JENNY

DACW61-78-C-0124

NL

UNCLASSIFIED

1 OF 2
AD
A069943



LEVEL


①

PASSAIC RIVER BASIN
WANAQUE RIVER, PASSAIC COUNTY
NEW JERSEY

A069943

LAKE INEZ DAM

NJ 00228



**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

THIS DOCUMENT IS BEST QUALITY PRODUCT
YOU MAY FURNISH TO DDC CONTAINING A
REPRODUCED SOURCE OF PAGES WHICH ARE
THE PROPERTY OF DDC.



Approved for public release;
distribution unlimited

DDC FILE COPY

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

May, 1979

70 06 74 022

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00228	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake Inez Dam Passaic County, N.J.		5. TYPE OF REPORT & PERIOD COVERED (9) FINAL rept.
7. AUTHOR(s) (10) Robert J. Jenny P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Jenny-Leedshill Engineering 318 South Orange Ave. South Orange, N.J. 07079		8. CONTRACT OR GRANT NUMBER(s) (15) DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 126p.
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) (6) National Dam Safety Program, Lake Inez Dam (NJ-00228), Passaic River Basin, Wanaque River, Passaic County, New Jer- sey, Phase I Inspection Report.		12. REPORT DATE (11) May 79
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		13. NUMBER OF PAGES 75
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) Unclassified
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Dams Visual Inspection Spillway Seepage National Dam Inspection Act Report Lake Inez Dam N.J. Structural Analysis		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

410 891

JOB



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-D

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

29 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Lake Inez Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Inez Dam, a high hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage. Any remedial measures found necessary should be initiated within calendar year 1980. Make a topographic survey of the

NAPEN-D

Honorable Brendan T. Byrne

dam site and monument the results for use in future inspections.

c. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

(2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.

(3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.

(4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.

(5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.

(6) The trees adjacent to the sluice gate should be removed and the area restored in order to prevent root damage.

(7) The potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

(8) The dam should be inspected with the reservoir drained down below the spillway.

d. A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

Accession For	
NTIS GMAI	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Available/or special
A	23

NAPEN-D


Honorable Brendan T. Byrne

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Robert A. Roe of the Eighth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:
Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CNO29
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CNO29
Trenton, NJ 08625

LAKE INEZ DAM (NJ00228)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 3 and 20 December 1978 by Jenny-Leedshill Engineers under contract to the State of New Jersey. The State, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Lake Inez Dam, a high hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage. Any remedial measures found necessary should be initiated within calendar year 1980. Make a topographic survey of the dam site and monument the results for use in future inspections.

c. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

(2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.

(3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.

(4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.

(5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.


(6) The trees adjacent to the sluice gate should be removed and the area restored in order to prevent root damage.

(7) The potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

(8) The dam should be inspected with the reservoir drained down below the spillway.

d. A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

APPROVED:


JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE:

29 May 1979

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake Inez
Federal I.D. No. NJ 00228
New Jersey I.D. No. 23-89
State Located: New Jersey
County Located: Passaic
Stream: Wanaque River
Date of Inspection: December 3 and 20, 1978

Brief Assessment of General Condition of Dam

The visual inspection indicates that the dam is in generally poor overall condition due to lack of maintenance.

The spillway of Lake Inez Dam is capable of passing approximately 10 percent of the Probable Maximum Flood and is considered inadequate.

The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right end of the dam, is threatened due to severe erosion of its rubble masonry foundation. There is cracking and leakage at the left abutment of the spillway and water is also leaking through the abandoned penstock and 8-inch diameter pipe. The structural stability of the dam cannot be quantitatively analyzed due to lack of available data.

The following recommendations should be implemented as soon as possible:

- 1) More sophisticated and detailed hydrologic and hydraulic analyses of the spillway capacity should be performed. From this, a positive action program of corrective measures should be developed and implemented as necessary.

2) Additional effort should be made to obtain information regarding the dam, including design and construction data from the owners.

3) A program of measurements and borings and laboratory tests should be conducted soon to determine the properties of the dam and foundation materials, so that seepage and stability analyses can be performed.

4) The dam should be inspected after the reservoir has been drained down below the spillway.

5) A warning system to alert downstream inhabitants in case of dam failure should be implemented.

6) The seismicity at the dam site and its effect on the stability of the dam should be investigated.

The following actions should be performed in the near future, taking advantage of the above:

1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

2) The foundation of the mill should be repaired.

3) The cracks adjacent to the left spillway abutment should be repaired.

4) The intake to the penstock and 8-inch diameter pipe should be completely sealed.

5) A program of inspections of the dam before and after floods and annually should be initiated.

6) The notch on the left side of the dam should be filled with concrete to elevation of the crest of the dam.

7) The trees adjacent to the the sluiceway should be removed.


Frank L. Panuzio

Frank L. Panuzio, P.E.
Project Engineer

Robert J. Jenny

Robert J. Jenny, P.E.
Project Director

ii New Jersey License #9878




View




LAKE INEZ DAM

2

w of dam looking upstream.
(Dec. 3, 1978)





3

TABLE OF CONTENTS

	Page
BRIEF ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTOGRAPH OF DAM	
PREFACE	iii
SECTION 1 PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	3
SECTION 2 ENGINEERING DATA	
2.1 Design	6
2.2 Construction	7
2.3 Operation	7
2.4 Evaluation	8
SECTION 3 VISUAL INSPECTION	
3.1 Findings	9
SECTION 4 OPERATIONAL PROCEDURES	
4.1 Procedures	13
4.2 Maintenance of Dam	13
4.3 Maintenance of Operating Facilities	13
4.4 Description of Warning System	13
4.5 Evaluation of Operational Adequacy	13
SECTION 5 HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	15
SECTION 6 STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	20

TABLE OF CONTENTS

(Continued)

	Page
SECTION 7 ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES	
7.1 Dam Assessment	22
7.2 Remedial Measures	24

PLATES

1. Regional Vicinity Map
2. Generalized Plan

APPENDICES

APPENDIX A - Check List - Visual Observations
Check List - Engineering, Construction
Maintenance Data

APPENDIX B - Photographs

1. Left abutment of dam
2. Left spillway abutment
3. Mill at right abutment of dam
4. Mill foundation
5. Spillway crest
6. Spillway face
7. Spillway face
8. Abandoned penstock
9. Sluice gate
10. Reservoir
11. Downstream channel
12. Downstream channel

APPENDIX C - Regional Geology - Highlands

APPENDIX D - Hydrologic and Hydraulic Computations

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

LAKE INEZ DAM

Federal I.D. No. NJ 00228
New Jersey I.D. No. 23-89

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act, Public Law 92-367, 1972, provides for the National Inventory and Inspection Program by the U. S. Army Corps of Engineers. This report has been prepared in accordance with this authority, through contract between the State of New Jersey and Jenny-Leedshill Engineers. The State of New Jersey has also entered into an agreement with the U. S. Army Engineer District, Philadelphia, to have this work performed.

b. Purpose of Inspection

The purpose of this inspection was to evaluate the general structural integrity and hydraulic adequacy of the dam, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Description of Dam and Appurtenance

The dam is an ashler masonry structure, the main part of which is a centrally located spillway 206 feet long and approximately 15 feet high. The spillway crest has a 5-foot wide concrete cap, and a concrete apron extends about 15 feet downstream.

The left side of the dam consists of a concrete capped masonry wall which is approximately 65 feet long and 2.6 feet higher than the spillway crest. A masonry wall, the top of which is at the same elevation as the spillway crest, extends 90 feet downstream from the left abutment of the spillway and retains earthfill through which a penstock passes. The end of the now abandoned 5-foot wide oval penstock extends through a masonry wall as shown on Plate 2.

The section of the dam adjacent to the right spillway abutment consists of a masonry wall which extends approximately 5 feet above the crest of the spillway. The configuration of this section of the dam, which also forms the right spillway training wall, is shown on Plate 2. The right side of the dam is formed by the foundation of a now abandoned mill building.

A 9.4-foot wide sluiceway with a slide gate consisting of wooden 4-inch by 8-inch wooden planks is located to the left of the abandoned mill building.

b. Location

Lake Inez Dam is located in north central New Jersey on the Wanague River in the Borough of Pompton Lakes, Passaic County. The regional vicinity plan is presented on Plate 1.

c. Size Classification

The storage capacity of Lake Inez is 470 acre-feet when the reservoir surface is at the top of dam. The dam is 17.6 feet high; therefore, the size classification of the dam is Small.

The criteria for size classification of dams are set forth in the Corps' Guidelines. A small size dam is one in which the reservoir capacity is greater than or equal to 50 acre-feet and less than 1000 acre-feet, and/or the maximum height is greater than or equal to 25 feet and less than 40 feet.

d. Hazard Classification

The dam is located in the Borough of Pompton Lakes

(population 11,500). A road and railroad bridge and at least 30 structures are located within the flood path downstream of the dam. Failure or misoperation of the dam could result in the loss of more than a few lives and excessive economic loss; therefore, the dam merits a High Hazard classification.

e. Owner

The dam is owned by Artistic Identifications Systems, Inc., Pompton Lakes, New Jersey.

f. Purpose of Dam

The dam was originally built to provide power to the owner's weaving factory adjacent to the dam. It is now used only for recreation.

g. Design and Construction History

There is no available information regarding the design of the dam. Drawings of the dam were reportedly destroyed in a fire.

The dam was reportedly built by Julius Smith, and a plaque on the dam adjacent to the mill building indicates that the dam was built in 1889. Discussions with a local resident indicated that the dam was destroyed by a flood in 1903; however, no information is available to confirm this, and the extent of damage is unknown.

h. Normal Operational Procedures

There is no known regulation of the dam or reservoir. The visual inspection indicates that the reservoir is designed to be emptied via the sluice at the right abutment; however, it appears that the gate is presently inoperable.

1.3 Pertinent Data

a. Drainage Areas (sq. Mi.)	98.1
b. Discharge at Damsite (cfs)	
* Ungated spillway capacity at maximum pool elevation	2,805

- c. Elevation (ft. above MSL)
- Top Dam 198.6
 - Spillway crest 196
 - Streambed at centerline of dam 181
- d. Reservoir Length (ft.)
- Maximum pool (top of dam) 7300
 - Recreation pool (Spillway crest) 7200
- e. Storage (acre-feet)
- Top of dam 470
 - Spillway crest 300
- f. Reservoir Surface (acres)
- Top dam 60
 - Spillway crest 51
- g. Dam
- Type Ashlar masonry dam
 - Length 345 ft. (approx.)
 - Height 17.6 ft.
 - Top Width 5 feet
 - Side Slopes Unknown
 - Zoning Unknown
 - Impervious Core Unknown
 - Cutoff Unknown
 - Grout curtain Unknown
- h. Spillway
- Type Masonry Dam
 - Length of weir 205.9 ft.
 - Crest elevation 196 ft.
 - U/S Channel Reservoir
 - D/S Channel Concrete apron

i. Regulating Outlets

- a) 5 ft. wide steel oval penstock at left abutment
- b) 9.4 ft. wide sluice with 4 in. x 8 in. wooden plank gate

SECTION 2: ENGINEERING DATA

2.1 Design

a. Geologic Conditions

Lake Inez Dam is located in north-central New Jersey very close to the eastern border of the Highlands physiographic province. The regional geology of the Highlands is discussed in Appendix C to this report.

The dam and its reservoir are situated in a long, narrow gorge which appears to be controlled by the underlying geologic structure. The linear, of which the gorge is a part, can be traced for more than 10 miles. A fault approximately one-quarter mile east of the left abutment is shown on New Jersey Geology Department maps, but no fault is shown in the valley bottom. However, a fault has been inferred by others upstream of the dam.

Bedrock is exposed on the left abutment of the dam. The rock appears to be primarily a pink tinted, white and black gneiss with distinct gneissic banding and a high percentage of quartz. A hard, finely crystalline, dark mafic rock is exposed within the gneissic mass which may be a dike, but vegetation and thin soil cover make the surficial tracing of the dike impractical. The bedrock extends all the way to the toe of the left abutment and it would appear that this abutment was constructed directly on the rock.

No bedrock exposures were observed under the dam or on the right abutment which has been completely altered by the construction of roadways and a large factory. Behind the factory, approximately 300 yards from the

abutment, bedrock is exposed, similar to that seen on the left abutment. There are no indications of whether the major part of the dam is built on bedrock or overburden.

Soil in the area appears to be primarily glacial till with recent alluvium in the bottom of the stream and in the flood plain.

The dam is located less than one-half mile from the long, continuous Ramapo Fault which divides the New Jersey Highlands from the Piedmont Lowlands. Several small earthquakes have occurred recently along this fault and it is currently under study as an "active" fault by Columbia University's Lamont-Doherty Geophysical Laboratory.

b. Design Data

There are no available data regarding the design of the dam. Drawings of the dam were reportedly destroyed in a fire.

2.2 Construction

The dam was reportedly built by Julius Smith and a plaque on the dam adjacent to the mill building indicates that the dam was built in 1889. Discussions with a local resident indicate that the dam was destroyed by a flood in 1903; however, no information is available to confirm this and the extent of damage is unknown.

A raceway through the base of the mill at the right abutment has been sealed with concrete blocks. The penstock at the left abutment has been abandoned and the power plant removed.

2.3 Operations

There is no known regulation of the dam or reservoir.

The visual inspection indicates that the reservoir is designed to be emptied via a sluiceway adjacent to the mill; however, the gate lift mechanism is presently broken.

2.4 Evaluation

a. Availability

No data regarding the design, construction or operation of the dam were made available by the owners of the dam. Available data consist of an inspection report prepared by the State in 1960 and "Dams in New Jersey - Reference Data" dated September 14, 1965. These data are included in Appendix D.

b. Adequacy

The structural stability of the dam cannot be evaluated due to the complete absence of any design and construction data.

c. Validity

The observations made during the 1960 inspection were generally confirmed by the present inspection.

Limited information regarding the history of the dam were obtained from a local resident; however, this information could not be substantiated.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

Visual inspections of Lake Inez Dam were made on December 3 and 20, 1978. The level of the reservoir was approximately 2 inches above the crest of the spillway during the December 3, 1978 inspection.

Visual inspection indicates that the dam is in need of remedial work to assure continued structural integrity. The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right side of the dam, is threatened due to severe erosion of its rubble masonry foundation.

Detailed inspection was made of the dam, appurtenant structures, reservoir and downstream channel. Descriptions of the findings of those inspections are summarized in the paragraphs which follow. The check list of visual inspection items is included in Appendix A. Geologic and foundation conditions observed at the time of inspection are noted in greater detail in Section 2.

b. Dam

The dam was inspected for signs of settlement, seepage, erosion, cracking and any other evidence of undesirable behavior which might affect the stability of the structure.

The wall forming the left side of the dam bends upstream but it appears that this alignment has existed for some time and no signs of recent movement were detected.

The left side of the dam is founded on rock and a deposit of soil has formed a beach on the upstream side at the left abutment. (Photo 1)

Severe cracking and separation between the concrete cap and masonry were observed at the junction of the left side of the spillway and the dam (Photo 2). Water from the reservoir is leaking through these cracks at an estimated rate of 5 gpm, forming a pond 6 to 12 inches deep. (Plate 2). There is a notch in the left side of the dam approximately 2 feet deep and 6 feet long which may have been associated with the penstock which appears to pass beneath the dam at this location.

Some minor seepage was noted through the masonry retaining wall which extends downstream from the left spillway abutment but it otherwise appears to be in good condition.

The section of the dam to the right of the spillway appears to be in generally good condition with the exception of some small trees that are growing next to, and in some places in, the masonry structure.

At the right abutment, the foundation of a mill building acts as part of the dam (Photo 3). A raceway which originally passed through the mill has been sealed with concrete bricks. The rubble masonry foundation of this building on the downstream side has been severely eroded (Photo 4). The erosion is most severe on the east side adjacent to the sluiceway and particularly at the downstream corner of the building. A minor amount of seepage through the foundation of this building was also observed.

c. Appurtenant Structures

Spillway

The spillway occupies the central section of the dam and turns at an angle approximately 30 feet from the right abutment. (Photo 6)

The ashlar masonry spillway structure has a concrete cap approximately 5 feet wide. This cap is generally set upstream of the masonry face except along a section approximately 25 feet long adjacent to the left abutment. This offset in the position of the spillway crest is shown in Photo 6 and is made most obvious by the different characteristics of flow over the spillway. Water flowing over the spillway obscured this structure so that the offset in the spillway crest and the face of the spillway could not be closely observed.

A concrete apron extends 10 to 15 feet downstream from the dam. (Photos 5 through 7) The foundation of the spillway and apron were submerged and therefore could not be observed.

Five loose stones, similar to those that comprise the downstream face of the spillway structure, are lying on the spillway apron (Photo 7). However, due to the flow of water over the spillway, it could not be determined if these stones were dislodged from the spillway.

Outlet Works

An abandoned 5-foot wide steel, oval penstock and an 8-inch diameter steel pipe were observed on the downstream side of the left abutment of the dam (Plate 2 and Photo 8). Water was leaking through both these outlets at a rate of about 10 gpm. There is presently no indication of a power plant or other similar structure in the vicinity

of the penstock.

A 9.4-foot wide sluice gate consisting of 4-inch by 8-inch boards is located to the left of the mill at the right side of the dam. The gate controls are inoperable and there is serious leakage between the boards (Photo 9). A small tree growing in the masonry wall adjacent to the sluice is shown in Photo 9. The discharge from the sluice flows adjacent to the old mill and joins the main channel downstream as shown in Plate 2.

A raceway through the mill has been sealed off as discussed above.

d. Reservoir Area

The reservoir is relatively narrow, and trends north-south. The slopes are generally gentle to moderately steep, and heavily wooded. The owner's factory buildings occupy the right bank immediately upstream from the dam (Photo 10).

There was a minor amount of debris in the reservoir and at the spillway crest. There was no indication that sedimentation is excessive.

d. Downstream Channel

The slopes of the channel directly downstream from the dam are moderately steep and covered with grass and some trees (Photo 11).

A steel road bridge in the Borough of Pompton Lakes is located approximately 500 feet downstream from the dam (Photos 11 and 12).

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

There is no known regulation of the reservoir, since all outlets either have been abandoned or are inoperable. The former raceway through the mill has been sealed off and the penstock at the left abutment has been abandoned. Controls for the timber sluice gate adjacent to the mill are broken and inoperable.

4.2 Maintenance of Dam

There are no records available regarding maintenance of the dam, and, based on the visual inspection, little, if any, maintenance work has been done in recent years. There are no instrumentation or monitoring systems on the dam or reservoir.

4.3 Maintenance of Operating Facilities

No maintenance records of operating facilities are available. The timber sluice gate is leaking and the controls are broken.

4.4 Description of Warning Systems

There is no warning system or emergency contingency plan in event of flooding or possible failure of the dam.

4.5 Evaluation of Operational Adequacy

The present operation and maintenance of the dam is deficient. It appears that there has been little maintenance

of the dam. The disrepair of the sluice gate is a serious operational deficiency since this gate is now the only reservoir outlet.

A warning system is needed to alert downstream inhabitants in time of floods and possible overtopping or failure of the dam.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data

As already stated, in Section 1.2, Lake Inez Dam is classified as high hazard and small in size. In accordance with the Corps of Engineers', "Recommended Guidelines for Safety Inspection of Dams," the Spillway Design Flood (SDF) should be 50% to 100% of the Probable Maximum Flood (PMF). The 100% PMF was selected as the SDF because of the high hazard to loss of life immediately downstream of the dam.

Data obtained from the Corps indicates the drainage basin area of Lake Inez Dam is 98.1 square miles. This drainage basin was divided into three sub-basins: one above Skyline Dam No. 1 having a drainage area of 2.9 square miles; another above Raymond Dam, which impounds Wanaque Reservoir, having a drainage area of 90.4 square miles; and the third sub-basin between Wanaque Reservoir, Skyline Lake No. 1 and Lake Inez having a drainage area of 4.8 square miles. The drainage sub-basins are delineated on a U.S.G.S. topographic map and presented on Plate D-1, Appendix D.

The hydraulic and hydrologic features of Lake Inez Dam were evaluated using criteria set forth in the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", and additional guidance and criteria provided by the Philadelphia District, Corps of Engineers. The PMF outflow hydrograph from the Wanaque Reservoir sub-basin was supplied by the Corps and used in the analyses. The PMF outflow hydrograph from Skyline Lake No. 1 was

previously calculated by Jenny-Leedshill and, as requested by the Corps, was used in this analysis. The Probable Maximum Precipitation (PMP) for the sub-basin between Wanaque Reservoir, Skyline Lake No. 1 and Lake Inez was calculated using Hydrometeorological Report No. 33 and the Hop Brook reduction factor for misalignment for the storm. The PMF for this sub-basin was calculated using the Corps' computer program HEC-1, Dam Break Version (HEC-1,DB). The Corps requested that the Snyder Unit Hydrograph with C_t and C_p coefficients of 2.0 hours and 0.63 hours, respectively, be used to calculate the PMF.

In computing the PMF for the sub-basin between Wanaque Lake, Skyline Lake No. 1 and Lake Inez, an initial infiltration loss of 0.5 inch and a final infiltration loss rate of 0.05 inch per hour were used in the HEC-1,DB program to give excess rainfall. Using the excess rainfall and the unit hydrograph, the program computed the peak inflow discharges from the sub-basin of the 10 percent, 25 percent, 50 percent and 100 percent PMF. These discharges are approximately, 1,210 cfs, 3,040 cfs, 6,070 cfs and 12,140 cfs, respectively.

As previously stated, the PMF outflow hydrograph from Wanaque Reservoir was supplied by the Corps. The PMF peak outflow from Wanaque Reservoir is 23,300 cfs. The PMF outflow hydrograph from Skyline Lake No. 1, as previously calculated by Jenny-Leedshill, is 10,600 cfs. This peak outflow was calculated assuming both Skyline Lake Dam No. 1 and the upstream Skyline Lake Dam No. 2 breach due to overtopping. The PMF outflow hydrographs from Wanaque Reservoir and Skyline Lake No. 1 were multiplied by 0.1, 0.25, and 0.5 to provide estimates of the 10 percent, 25 percent and 50 percent PMF.

The various percentages of the PMF hydrograph from Skyline Lake No. 1 were routed downstream through three successive reaches to the Wanaque River. These floods were then combined with the corresponding percentage PMF outflows from Wanaque Reservoir. The combined hydrographs were then routed downstream to Lake Inez and combined with the runoff from the intermediate basin. The peak inflow discharges into Lake Inez for the 10 percent, 25 percent, 50 percent, and 100 percent PMF were calculated to be approximately 2,930 cfs, 7,420 cfs, 15,000 cfs and 30,000 cfs, respectively.

The various percentages of the PMF inflow hydrograph were routed through Lake Inez using the Modified Puls Method by the HEC-1,DB program. The peak outflow discharges of the 10 percent, 25 percent, 50 percent and 100 percent PMF were calculated to be approximately 2,880 cfs, 7,280 cfs, 14,510 cfs and 28,710 cfs, respectively. The flood routings indicate that all floods greater than about 10 percent of the PMF will overtop the dam. A plot of percent PMF versus peak outflow discharge is presented as Plate D-2 in Appendix D.

The spillway and overtop stage-discharge rating curve used in the flood routings through Lake Inez was calculated using the weir equation. Tailwater effects, caused by a constriction in the downstream channel, were considered in developing the rating curve. The spillway and dam crest is a 5-foot wide weir with an estimated discharge coefficient of 3.1. The reservoir stage-storage curve was determined from U.S.G.S. 7.5 - minute topographic maps and data obtained from State files. This stage-storage curve was extended above the dam crest to include surcharge storage

during peak flood discharges. In the reservoir routing computations possible discharges through the outlet works were excluded because their capacity is small compared to the PMF and because of the possibility that they may be closed or inoperable. The stage-storage and the spillway and overtop stage-discharge curves are presented in Appendix D as Plates D-3 and D-4, respectively.

The various percentage PMF outflow hydrographs from Lake Inez were routed 0.5 miles downstream through two successive reaches through the Borough of Pompton Lakes. These routings were made to determine downstream flooding characteristics. These characteristics are presented in the following tabulation. The hydraulic parameters used in the HEC-1,DB program for the downstream routing calculations were estimated based on observations made in the field and information obtained from U.S.G.S. topographic maps.

FLOODING CHARACTERISTICS AT THE BOROUGH OF POMPTON LAKES

	<u>10% PMF</u>	<u>25% PMF</u>	<u>50% PMF</u>	<u>100% PMF</u>
Peak Discharge, cfs.	2,890	7,270	14,510	28,770
Maximum Stage, ft.	190.6	195.2	199.5	204.3

In the Borough of Pompton Lakes there appears to be at least 30 structures below elevation 200 feet. During large floods several of these structures could sustain severe damage and loss of life could result.

There were three outlet structures at Lake Inez. Two of the outlets have been abandoned. The third outlet is a small sluiceway with a timber gate. The gate is in very poor condition but could be removed if lake drawdown were required. A rating curve for the sluiceway, assuming the gate is removed, was estimated using the weir equation.

Using this rating curve and assuming no inflow into the lake and no tailwater effects, the time required to drain the reservoir from a spillway full condition was calculated to be about 13 hours.

b. Experience Data

Records of lake levels are not maintained for this site. The dam which originally was built to supply water and power to an old adjacent mill, is now used for recreational purposes.

c. Visual Observations

There is a well defined channel downstream of the dam. There are structures on both banks. There is a bridge approximately 500 feet downstream of the dam. The banks downstream are tree lined with little undergrowth. The overbank slopes are gentle, and include open areas, wooded areas, and residential and commercial areas.

d. Overtopping Potential

As indicated in Section 5.1-a, the Lake Inez Dam spillway can pass only 10 percent of the PMF. During the PMF the dam would be overtopped 11.8 feet.

During large floods the water surface elevation downstream of the spillway is only slightly less than the upstream elevation because of a constriction in the downstream channel. The tailwater effect limits the flood's capacity to erode a breach in the embankment and limits the static forces on the masonry portion of the dam. There is some question as to whether these forces would be adequate to cause a dam breach. In addition, the channel constriction limits the downstream discharge such that a dam breach would increase the downstream discharge only a small amount. Thus, the spillway for Lake Inez Dam should be classified as inadequate.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

Visual inspection indicates that the dam is in need of remedial work to assure continued structural integrity. The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right side of the dam, is threatened due to severe erosion of its rubble masonry foundation, although the upstream face of the foundation is newer and in better condition. Some cracking and leakage was observed at the left abutment of the spillway and water is also leaking through the abandoned penstock and 8-inch diameter pipe.

Water flowing over the spillway obscured inspection of this structure. Several large masonry stones are lying on the concrete apron; however, it could not be determined if these stones have been dislodged from the spillway. In addition, the condition of the spillway foundation could not be inspected.

b. Design and Construction Data

There are no available data regarding the design and construction of the dam or outlet works; therefore, the structural stability of the dam cannot be evaluated. Nothing is known of the core of the dam, the foundation, or the cross sectional configuration.

c. Operating Records

The reservoir is uncontrolled and there is no

instrumentation of the dam. Records of reservoir levels and water withdrawals are not available. A brief inspection report was made by the State in 1960 and is included in Appendix D, page D-41.

d. Post-Construction Changes

The original dam was reportedly destroyed by a flood in 1903; however, there is no documentation to confirm this nor descriptions of re-construction.

A raceway through the foundation of the mill building has been sealed off with concrete blocks. The penstock at the left abutment has been abandoned and the power generating equipment removed.

e. Seismic Stability

The dam is located in Seismic Zone 1, in which it may generally be assumed that there is no hazard from earthquakes, provided static stability conditions are satisfactory and conventional safety margins exist. However, as pointed out in Section 2.1-a, the dam is located less than one-half mile from the seismically active Ramapo Fault. In addition, the reservoir is situated in what is thought to be a structurally controlled valley and a fault has been inferred by others upstream from the reservoir. Data are insufficient at this time to assess seismic stability, should a significant earthquake occur in the vicinity of the dam.

SECTION 7: ASSESSMENT, RECOMMENDATIONS,
PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The spillway of Lake Inez Dam can pass only about 10% of the probable Maximum Flood and is considered inadequate.

The structural stability of the dam cannot be quantitatively analyzed due to lack of available data. The visual inspection indicates that the dam is in generally poor condition and has not been well maintained. The wooden sluice gate is leaking badly and the lift mechanism is broken. The foundation of the mill building at the right side of the dam is badly deteriorated, except on the upstream side, and its failure could cause failure of the upstream side which acts as part of the dam. There is some leakage at the left abutment of the spillway, and water is also leaking through the abandoned penstock and 8-inch diameter pipe.

b. Adequacy of Information

The information and data obtained are not adequate to perform a comprehensive evaluation of the dam's structural stability because of an absence of data regarding the design and construction of the dam and as-built conditions.

c. Urgency

The visual inspection revealed deficiencies which

are detrimental to the integrity of the structure. Therefore, it is recommended that the owners perform the remedial measures discussed below as soon as possible. The most urgent items are the repair of the sluice gate and foundation of the mill.

d. Necessity for Additional Data/Evaluation

The main section of the dam was obscured by water overflow and could not be closely observed. Therefore, the dam should be inspected with the reservoir level far below the spillway crest.

The Corps of Engineers Guidelines require that, in general, seepage and stability analyses should be on record for all dams in the high hazard category. At the present time there are inadequate data to perform these analyses. Since none exist, every effort should be made as soon as possible to obtain data regarding the dam including design and construction information, from the owners. At the same time, because so little is known about the as-built condition of the dam and appurtenant structures, and because of the high hazard downstream, a timely program of measurements and borings and laboratory tests of the dam and foundation should be undertaken soon so that seepage and stability analyses can be performed and the safety of the dam evaluated.

The hydrologic analysis indicates that the spillway is inadequate. Therefore, more sophisticated and detailed hydrologic and hydraulic analyses of the spillway capacity should be performed as soon as possible. From this, a positive action program of corrective measures should be developed and implemented as necessary.

Although the dam is located in Seismic Zone 1, it is situated in a valley which was possibly formed as the result of faulting and is in close proximity to the seismically active Ramapo Fault. Therefore, the potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

7.2 Remedial Measures

a. Repair Procedures

It is recommended that the following remedial measures be performed as soon as possible.

- 1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.
- 2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.
- 3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.
- 4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.
- 5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.


b. Operation and Maintenance Procedures

A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary.

A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

The trees adjacent to the sluice gate should be removed soon and the area restored in order to prevent root damage.

A warning system should be established whereby downstream inhabitants can be notified and evacuated in the event of possible dam failure.




AREA LOCATION

VICINITY MAP

JENNY - LEEDSHILL

FEBRUARY 1979



LAKE INEZ DAM

GENERALIZED PLAN BASED ON VISUAL
INSPECTION, DECEMBER 3, 1978

JENNY - LEEDSHILL

JANUARY 1979

Not to scale

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION
MAINTENANCE DATA

Check List
Visual Inspection
Phase 1

Name Dam Lake Inez County Passaic State New Jersey Coordinators NJDEP
 Date(s) Inspection Dec. 3 & 20, 1978 Weather Overcast Temperature 36°
 Coordinates: Lat. 41° 00' 30"
 Long. 74° 17' 30"

Pool Elevation at Time of Inspection 196 M.S.L. Tailwater at Time of Inspection 182 M.S.L.
 (approx.) (approx.)

Inspection Personnel:

<u>R. C. Gaffin</u>	<u>(Dec. 3, 1978)</u>
<u>A. R. Slaughter</u>	<u>R. J. Jenny</u>
<u>P. L. Wagner</u>	<u>D. J. Lachel</u>
	<u>F. L. Panuzio</u>
	<u>A. R. Slaughter</u>

Robert C. Gaffin Recorder

CONCRETE/MASONRY DAMS

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	<p>-Water was leaking through the left abutment of the spillway at a rate of about 5 gpm</p> <p>-The face of the dam could not be inspected for seepage or leakage due to water passing over the dam.</p>	<p>-Minor seepage through foundation of mill building at right abutment and left wing walls.</p> <p>Left abutment of spillway should be sealed to prevent leaking.</p>
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	<p>-Left abutment is founded on rock</p> <p>-Old mill building at right abutment. Previous raceway through mill has been walled off with concrete blocks.</p>	
DRAINS	None observed	
WATER PASSAGES	-See 'Outlet Works'	
FOUNDATION	<p>-Rock outcropping at left abutment</p> <p>-Rubble masonry foundation at mill building was significantly eroded</p>	Foundation of abandoned mill at right abutment should be repaired

CONCRETE/MASONRY DAMS

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	<ul style="list-style-type: none"> - Several surface cracks noted in concrete cap of masonry walls at left and right abutments - Some mortar is missing from masonry wall adjacent to sluiceway at right abutment 	
STRUCTURAL CRACKING	<ul style="list-style-type: none"> - Concrete on left wall adjacent to spillway is in poor condition and separating from masonry. 	
VERTICAL AND HORIZONTAL ALIGNMENT A-3	<ul style="list-style-type: none"> a) Wall at left abutment bowed upstream b) Crest of overflow section is set back from masonry face of dam except + 25 ft. section at left where the cap extends further D/S than masonry face 	
MONOLITH JOINTS	None observed	
CONSTRUCTION JOINTS	None observed	

EMBANKMENT
(None)

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Not applicable	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Not applicable	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Not applicable	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Not applicable	
RIPRAP FAILURES	Not applicable	

EMBANKMENT
(None)

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VEGETATION	Not applicable	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Not applicable	
ANY NOTICEABLE SEEPAGE	Not applicable	
STAFF GAGE AND RECORDER	Not applicable	
DRAINS	Not applicable	

OUTLET WORKS

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not applicable	
INTAKE STRUCTURE A-6	Intake to the raceway through base of abandoned mill has been sealed with concrete blocks	
OUTLET STRUCTURE	<p>a) Mechanically operated wooden sluice gate 9.4' wide located to the left of the mill building. Water is leaking between 4" x 8" wooden boards. Small tree is growing from masonry wall to the left of gate.</p> <p>b) Abandoned 5 ft. wide steel oval penstock and 8 in. diameter steel pipe at downstream end of left wing wall, leaking at a rate of approx. 10 gpm.</p>	<p>a) Sluice gate should be replaced and tree should be removed</p> <p>b) Intake to penstock and 8" pipe should be sealed</p>
OUTLET CHANNEL	Unlined channel downstream of sluice gate passes along the foundation of the abandoned mill and enters the main downstream channel. Water was about 1 ft. deep during inspection. Boulder blocking channel 15 ft. D/S from gate	
EMERGENCY GATE	See above	

UNGATED SPILLWAY

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	<ul style="list-style-type: none"> - Concrete cap approximately 5 ft. wide. Cap is generally upstream of masonry face of dam except the + 25 ft. at left where the crest extends further D/S than face. - Few eroded notches in crest 	
APPROACH CHANNEL A-7	Reservoir	
DISCHARGE CHANNEL	<ul style="list-style-type: none"> - Concrete apron extends 10' to 15' downstream - 5 large masonry stones, similar to those in dam, are on apron - Minor debris at base of spillway 	Stones on spillway apron may have been dislodged from dam.
BRIDGE AND PIERS	None	

GATED SPILLWAY
(None)

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Not applicable	
APPROACH CHANNEL	Not applicable	
DISCHARGE CHANNEL	Not applicable	
BRIDGE AND PIERS	Not applicable	
GATES AND OPERATION EQUIPMENT	Not applicable	

INSTRUMENTATION (None)

Lake Inez Dam

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

RESERVOIR

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Slopes are generally gentle to moderately steep and wooded. Industrial development on right bank.	
SEDIMENTATION	Sedimentation does not appear to be excessive. Minor debris at spillway crest.	

DOWNSTREAM CHANNEL

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Steel road bridge approximately 500 ft. D/S and Borough of Pompton Lakes. Rail- road bridge about 1,000 ft. D/S from road bridge Minor debris	
SLOPES A-11	Moderately steep slopes with grass and moderate growth of trees	
APPROXIMATE NO. OF HOMES AND POPULATION	Numerous homes, businesses and roads in Pompton Lakes at elevations below the crest of the dam.	

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

ITEM	REMARKS
PLAN OF DAM	None
REGIONAL VICINITY MAP	Dam and reservoir are shown on U.S.G.S. Wanaque Quadrangle, scale 1:24,000
CONSTRUCTION HISTORY A-12	Plaque on dam gives construction date of 1889.
TYPICAL SECTIONS OF DAM	None
HYDROLOGIC/HYDRAULIC DATA	None
OUTLETS - PLAN - DETAILS -CONSTRAINTS -DISCHARGE RATINGS	None None None None
RAINFALL/RESERVOIR RECORDS	None

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

ITEM	REMARKS
DESIGN REPORTS	None
GEOLOGY REPORTS	None
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES P-13	None
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	Unknown

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

ITEM	REMARKS
SPILLWAY - PLAN	None
-SECTIONS	None
-DETAILS	None
OPERATING EQUIPMENT PLANS & DETAILS	None
MONITORING SYSTEMS P-14	None
MODIFICATIONS	Raceway through mill at right abutment has been sealed off and penstock at left abutment has been abandoned.
HIGH POOL RECORDS	None
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	a) "Report on Dam Inspection", by Michael J. Galley, June 2, 1960 b) "Dams in New Jersey - Reference Data," dated Sept. 14, 1965
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Verbal report indicates dam was destroyed by flooding in 1903.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

REMARKS

ITEM

MAINTENANCE
OPERATION
RECORDS

None

APPENDIX B
PHOTOGRAPHS

(Note: All photographs were taken on Dec. 3, 1978)



Photo 1
View of left abutment of dam looking west



Photo 2
View of left spillway abutment looking west



Photo 3
View of mill at right
abutment of dam looking east



Photo 4
View of mill foundation
looking west with sluiceway in foreground



Photo 5
View along spillway crest
looking towards left abutment



Photo 6
View of spillway face
looking west from left abutment



Photo 7
View of spillway face
showing loose stones on apron



Photo 8
View of abandoned penstock and
8 inch diameter pipe looking upstream



Photo 9
View of sluice gate
looking upstream



Photo 10
View of reservoir looking upstream from dam




Photo 11
View of road bridge and
Borough of Pompton Lakes downstream from dam



Photo 12
View of dam looking
upstream from bridge shown in Photo 11

APPENDIX C

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

Physiography

The New Jersey Highlands extend northeast-southwest across the state from the New York border to the Delaware River. Included in the province are the northwest portions of Hunterdon, Passaic and Morris Counties and the southeastern portions of Warren and Sussex Counties. This province lies between the Appalachian Ridge and Valley Province to the northwest and the Piedmont Lowlands Province to the southeast (See Figure C-1) and is part of the larger New England Physiographic Province.

The Highlands are characterized by rounded and flat-topped northeast-southwest ridges and mountains up to 1,400 feet high separated by narrow valleys. The orientation of the valleys is usually, but not always, controlled by the underlying geologic structure.

Bedrock


Bedrock of the region is predominantly Precambrian gneisses, schists and metasediments. Some sedimentary rocks, typically sandstones, shales and conglomerate have been infolded and faulted into the valley bottoms.

The regional geologic structure reflects the very old age of bedrock. A number of regional faults cross the area in a northeast-southwest direction. The Ramapo Fault scarp, forming the eastern border of the province, is more than 30 miles long. Faults also control many of the river valley orientations.

Mountain crests slope uniformly from northwest to southwest, a direct result of the fact that the entire area was once part of the now dissected Schooley peneplain.

Overburden

Much of the province was covered by the Pleistocene age Wisconsin glacier. The glacier stripped most of the existing overburden and weathered rock and uncovered the numerous hard bedrock knobs and ridges seen throughout the province. Most of the side-slopes in the area are covered with heavy boulder tills (ground moraine), while glacial outwash and recent alluvium cover the valleys. South of the terminal moraine extending from Morristown to Belvidere, scattered remnants of earlier stages of glaciation (Illinoian and Kansan) have deposited ground moraine (glacial tills) over the bedrock. In the valleys and over some of the ground moraine, recent and glacio-fluvial alluviums have been deposited.



SCHEMATIC CROSS-SECTION OF
NEW JERSEY HIGHLANDS
PHYSIOGRAPHIC PROVINCE
(AFTER WOLFE, 1977)

JENNY/LEEDSHILL
JANUARY 1979

FIGURE C-1

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

LAKE INEZ

CHECK LIST HYDROLOGIC AND HYDRAULIC DATA ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 98.1 SQ. MILES

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 196 FT (300 AF)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 198.5 (460 AF)

ELEVATION MAXIMUM DESIGN POOL: _____

ELEVATION TOP DAM: 198.5 FT

CREST: SPILLWAY

- a. Elevation 196.0
- b. Type MASONRY OUTFLOW
- c. Width 5'
- d. Length 206 FT
- e. Location Spillover CENTER OF DAM
- f. Number and Type of Gates NONE

OUTLET WORKS: IMPERFEABLE

- a. Type TEMPER SLUICeway
- b. Location _____
- c. Entrance inverts _____
- d. Exit inverts _____
- e. Emergency draindown facilities _____

HYDROMETEOROLOGICAL GAGES: NONE

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE: 2805 CFS (OVER SPILLWAY + OVER SLUICeway)

LAKE INEZ






FIGURE 2

SEASONAL VARIATION

DEPTH-AREA-DURATION RELATIONSHIPS

Percentage to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE ALL SEASON ENVELOPE



302-03



D-3


[illegible]

RBE 790201

LAKE INEZ

802-03

1/6

DISCHARGE OVER DAM

$$Q = CLH^{1.5}$$

$C = 3.1$ (BROADCRESTED WEIR) (EXCEPT SLUICWAY $C = 3.3$) ②

ELEV	H (FT)	Q (CFS)	H (FT)	Q (CFS)	H (FT)	Q (CFS)	H (FT)	Q (CFS)	Q TOTAL (CFS)
197	1	640	1	30					670
198	2	1810	2	80					1690
198.6	2.6	2680	2.6	125	0	0			2805
199	3	3320	3	155	0.4	50			3525
200	4	5110	4	240	1.4	330			5680
201	5	7140	5	330	2.4	750	0	0	8220
202	6	9390	6	440	3.4	1260	1	200	11290
203	7	11830	7	550	4.4	1860	2	590	14830
206	10	20190	10	940	7.4	4060	5	2250	27440
211	15	37104	15	1725	12.4	8800	10	6370	53995

② THIS DISCHARGE ASSUMES NO TAILWATER EFFECTS. IT WAS FOUND TAILWATER AT HIGHER DISCHARGES AFFECTED THE DISCHARGE.

LEEDS, HILL AND JEWETT, INC.

BY RBT DATE 7-10-42 CLIENT New Jersey

SHEET NO. 2 OF 6

CHKD. DATE JOB

JOB NO. 302-23

TAILWATER EFFECTS ON SPILLWAY DISCHARGE

DOWNSTREAM OF THE DAM THE CHANNEL NARROWS PRODUCING A BACKWATER WHICH SUBMERGES THE SPILLWAY AND REDUCES DISCHARGE CALCULATED PREVIOUSLY ASSUMING NO SUBMERGENCE. IN ORDER TO DETERMINE THE TAILWATER EFFECTS ON DISCHARGE A NUMBER OF ASSUMPTIONS WERE MADE.

- 1) FOR LARGE FLOWS THE WATER SURFACE ELEVATION @ THE DAM AND AT THE DOWNSTREAM SECTION, 400 FT FROM THE DAM ARE THE SAME.
- 2) FIG 252 IN DESIGN OF SMALL DAMS (USBR) CAN BE USED TO CALCULATE DISCHARGE REDUCTION DUE TO SUBMERGENCE FOR WEIR FLOW
- 3) THE STREAMBED ELEVATION BELOW THE DAM IS 183 EXCEPT AT THE LEFT ABUTMENT WHICH IS 3 FT BELOW THE WALL WITH AN ELEV. OF 185.6

METHOD: FOR A GIVEN DISCHARGE, AT THE DOWNSTREAM STATION THE DEPTH IS OBTAINED FROM A RATING CURVE USING MANNINGS EQU. A HEAD OVER THE DAM IS ASSUMED AND THE % REDUCTION IN DISCHARGE IS DETERMINED GRAPHICALLY (FIG 252 DESIGN OF SMALL DAMS) FOR ALL THREE SPILLWAYS WITH DIFFERENT CREST ELEVATIONS. THE FREE DISCHARGE IS DETERMINED FOR EACH SPILLWAY AND REDUCED BY THE ABOVE %. THE TOTAL CORRECTED DISCHARGE SHOULD EQUAL THE ORIGINAL DISCHARGE, IF NOT A NEW HEAD IS ASSUMED UNTIL THE SAME DISCHARGE IS OBTAINED

LEEDS, HILL AND JEWETT, INC.

BY RBE DATE 7/10/42 CLIENT New Jersey

SHEET NO 3 OF 6

CHKD DATE JOB

JOB NO. 302-03

Stream Elev for ① & ③ = 183 FT
② = 195.6 FT

Q ¹ BRIDGE CFS	d ¹ FT	Spillway	Assume H _e	hd ¹	hd H _e	hd + d H _e	% Reduc of Q	Q ³ BEFORE REDUCTION CFS	Total Q CFS
30150	27.26	1	15.1	28.1	0.056	1.86	45	39200	30690
	14.66	2	12.5	15.5	0.067	1.24	42	8400	
	27.26	3	10.1	28.1	0.083	2.78	39	6500	OK
24940	25.32	1	13.0	26.0	0.052	2.0	47	33200	24650
	12.72	2	10.4	13.4	0.065	1.29	40	6900	OK
	25.32	3	8.0	26.0	0.085	3.25	38	4700	
20490	23.37	1	11.1	24.1	0.066	2.17	41	25000	20620
	10.77	2	8.5	11.5	0.086	1.35	29	5100	OK
	23.37	3	6.1	24.1	0.12	3.95	28	3200	
13570	19.47	1	7.5	20.5	0.137	2.73	21	13800	13550
	6.87	2	4.9	7.9	0.21	1.61	9	2200	OK
	19.47	3	2.5	20.5	0.41	8.4	4	900	
8690	15.58	1	5.1	18.5	0.494	3.55	2.5	7800	8560
	2.98	2	2.5	5.5	1.01	2.20	0	900	OK
	15.58	3	0.1	18.1	25.2	18.1	0	50	

- 1 From HEC-1 Run Assuming no tailwater effects.
2 From Fig 252 DESIGN OF SMALL DAMS, USBR
3 FROM RATING CURVES ASSUMING NO SORBERGENCE PAGE 4
4 SUMMATION OF CORRECTED SPILLWAY DISCHARGES USING % REDUCTION OF Q

D-7



$\frac{4}{6}$

D-8
W.S.E.L. (FT)

SPILLWAY DISCHARGE (10000 CFS)

LEEDS, HILL AND JEWETT, INC.

BY RBE DATE 7/04/26 CLIENT NEW JERSEY

SHEET NO. 5 OF 6

CHKD. DATE JOB

JOB NO. 302-03

NORMAL DEPTH CHANNEL ROUTING

C BRIDGE

HEC-1 OUTPUT

QNI(1) QNI(2) QNI(3) FLNVT ELMAX RLNTH SEL
1000 16450 1000 193.0 220.0 400. 100100

CROSS SECTION COORDINATES—STA, ELEV, STA, ELEV—ETC
0.00 220.00 900.00 200.00 950.00 190.00 975.00 183.00 1025.00 183.00
1050.00 190.00 1100.00 200.00 1250.00 220.00

STORAGE	0.00	1.07	2.29	3.90	5.57	7.08	11.13	12.93	16.04	19.63
	24.61	31.43	40.07	50.34	62.93	76.96	92.91	110.70	130.31	151.74
OUTFLOW	0.00	166.74	563.66	1170.25	2071.51	3320.73	4836.20	6623.50	8648.90	10967.34
	13569.50	16724.25	20487.45	24938.91	30153.95	36205.67	43163.27	51042.64	60054.37	70121.65
STAGE	183.00	194.95	199.89	188.84	190.74	192.74	194.68	196.63	198.58	200.53
	202.47	204.42	205.37	208.32	210.26	212.21	214.16	216.11	218.05	220.00
FLOW	0.00	166.74	563.66	1170.25	2071.51	3320.73	4836.20	6623.50	8648.90	10967.34
	13569.50	16724.25	20487.45	24938.91	30153.95	36205.67	43163.27	51042.64	60054.37	70121.65

380

DESIGN OF SMALL DAMS





Figure 252. Effects of downstream influences on flow over weir crests. 288-D-2412.

RBE

790926

302-03

6/6

SPILLWAY RATING CURVE

D-10

RBC 740212 302-03 LAKE INEZ

DRAWDOWN CALCULATIONS

THERE ARE THREE OUTLETS ALL OF WHICH APPEARED INOPERABLE FROM FIELD INSPECTION. ONE OF THESE IS A TIMBER SLUICeway WHICH DOES NOT OPERATE BUT COULD BE EASILY DESTROYED IN CASE OF AN EMERGENCY DRAWDOWN. THEREFORE TIME REQUIRED TO CALCULATE DRAWDOWN WILL USE THIS GATE

$$Q = CLH^{1.5}$$

$C = 3.1$ AT BOTTOM OF SLUICeway / BROADCRESTED WEIR

$L = 9.4$ (9.4 FEET FROM INSPECTION REPORT JUNE 2 1960)

ASSUME: 1) NO INFLOWS INTO LAKE
2) NO TAILWATER EFFECTS

$$Q = 3.1 (9.4) H^{1.5} \quad Q = \Delta S / \Delta t$$

$$\Delta S / \Delta t = 29.1 H^{1.5}$$

$$\Delta t = (\Delta S / 29.1 H^{1.5}) (43560 \text{ FT}^3/\text{AF}) (1/3600 \text{ SEC}/\text{HR})$$

$$\Delta t = 0.42 H^{-1.5} \Delta S$$

ELEV. (FT)	STO (AF)	Δ STO (AF)	MEAN HEAD (FT)	Δ TIME (HR)	Σ TIME (HR)
196	300				
		95	13	0.85	
194	205	70	11	0.81	0.9
192	135	50	9	0.76	1.7
190	85	65	6	1.86	2.4
186	20	20	1	8.40	4.3
182	0				<u>12.7</u>

DRAWDOWN TIME = 12.7 HR

D-12

	1	2	ROUTING	-MODIFIED PULS-	STATION 1	TO 2
M						
K						
KL						
Y	1	1			230	150
Y	0.1	0.045	3.1	257	290	0.004
Y	0	0	1.0	282	493	560
Y	339	261	700	200	1150	290
Y	1	1				
KL						
Y						

101	Y6	C-1	9.045	0.10	293	240	MACO	0.002	203	1225	203
102	Y7	0	240	1300	220	1150	207	1150	207		
103	Y7	1225	207	1275	220	1400	240				
104	K	0									
105	K1										
106	K	1									
107	P	1	22.0	1.8	123	133	142				
108	F										
109	Y	2.0	0.63								
110	K	-1	-0.5	2.0							
111	K	2									
112	K1										
113	K	1									
114	K1										
115	Y										
116	Y1	1									
117	Y4	196	197	198	198.6	199	201.1	203.5	207.1	209	211.1
118	Y5	0	670	1390	2805	3525	4563	13550	20620	24650	30690
119	Y5	0	10	60	200	520	1000	1010	1800		
120	Y5	182	195	190	196	200	205	210	211.1		
121	Y5	196									
122	Y5	211.1	0	1.5	0						
123	K	1									
124	K1										
125	Y										
126	Y1	1									
127	Y4	0.1	0.045	0.1	183	220	400	0.001	183	1025	183
128	Y7	0	220	300	200	950	190	975			
129	Y7	1050	190	1100	200	1250	220				
130	K	1									
131	K1										
132	Y										
133	Y1	1									
134	Y5	0.1	0.045	0.1	181	220	2300	0.001	181	625	181
135	Y7	0	220	50	200	550	190	575			
136	Y7	650	190	800	200	2550	220				
137	K	99									

RUNOFF FROM AREA BETWEEN WAMAUQUE/SKYLINE AND INEZ
 COMBINE OUTFLOWS FROM SKYLINE AND WAMAUQUE WITH RUNOFF
 ROUTING COMBINED FLOWS THROUGH LAKE INEZ
 CHANNEL ROUTING -MODIFIED PULS- STATION 10 TO 11
 CHANNEL ROUTING -MODIFIED PULS- STATION 11 TO 12

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT
 ROUTE HYDROGRAPH TO
 ROUTE HYDROGRAPH TO
 ROUTE HYDROGRAPH TO
 RUNOFF HYDROGRAPH AT
 COMBINE 2 HYDROGRAPHS AT
 ROUTE HYDROGRAPH TO
 RUNOFF HYDROGRAPH AT
 COMBINE 2 HYDROGRAPHS AT
 ROUTE HYDROGRAPH TO
 ROUTE HYDROGRAPH TO
 ROUTE HYDROGRAPH TO
 END OF NETWORK

D-15

2017 M011715 -5700 0313J00H - 0M13N00 13hM7M2D

[illegible]

WATER DEPTH CHANNEL ROUTING

QM(1)	QM(2)	QM(3)	FLMVT	ELMAX	PLMTH	SEL
1000	.0450	.1000	297.0	290.0	150.	.60000

213--A773915, A773915--5414100003 4014335 55000

0.00	293.60	150.00	286.60	408.60	261.00	380.00	237.80	225.00	257.60
935.00	261.00	700.00	286.60	1150.00	290.00				

STAGE	0.60	-18	-6.0	1.74	3.36	6.50	8.66
	16.73	13.76	14.07	10.16	31.39	61.69	61.22
OUTFLOW	0.00	170.02	578.60	1310.03	6230.91	18000.68	18000.68
	21749.53	27779.71	34533.41	42189.61	50217.17	58365.62	115015.66
STAGE	237.00	799.74	260.43	262.21	263.68	276.13	272.63
	276.37	276.11	276.66	276.32	276.70	276.66	276.66
FLOW	0.00	170.02	578.60	1310.03	6230.91	18000.68	18000.68
	21749.53	27779.71	34533.41	42189.61	50217.17	58365.62	115015.66

CHANNEL ROUTING - MODIFIED PULS- STATION 2 TO 3

[illegible]

ON(1)	ON(2)	ON(3)	ELMVT	ELMAX	BLMTH	SEL
.0450	.0450	.0450	250.0	280.0	2750.	.00400

214--A473'VLS-A373'VLS--544410000 4011335 55000

0.00	290.00	1500.00	260.00	1150.00	25.00	1175.00	290.00
1175.00	253.00	1300.00	200.00	1000.00	280.00		

	5-CO	7-04	9-10	9-18	9-20	9-21	9-22	9-23	9-24	9-25	9-26	9-27	9-28	9-29	9-30	10-01	10-02	10-03	10-04	10-05	10-06	10-07	10-08	10-09	10-10	10-11	10-12	10-13	10-14	10-15	10-16	10-17	10-18	10-19	10-20	10-21	10-22	10-23	10-24	10-25	10-26	10-27	10-28	10-29	10-30	10-31	11-01	11-02	11-03	11-04	11-05	11-06	11-07	11-08	11-09	11-10	11-11	11-12	11-13	11-14	11-15	11-16	11-17	11-18	11-19	11-20	11-21	11-22	11-23	11-24	11-25	11-26	11-27	11-28	11-29	11-30	12-01	12-02	12-03	12-04	12-05	12-06	12-07	12-08	12-09	12-10	12-11	12-12	12-13	12-14	12-15	12-16	12-17	12-18	12-19	12-20	12-21	12-22	12-23	12-24	12-25	12-26	12-27	12-28	12-29	12-30	12-31	1-01	1-02	1-03	1-04	1-05	1-06	1-07	1-08	1-09	1-10	1-11	1-12	1-13	1-14	1-15	1-16	1-17	1-18	1-19	1-20	1-21	1-22	1-23	1-24	1-25	1-26	1-27	1-28	1-29	1-30	1-31	2-01	2-02	2-03	2-04	2-05	2-06	2-07	2-08	2-09	2-10	2-11	2-12	2-13	2-14	2-15	2-16	2-17	2-18	2-19	2-20	2-21	2-22	2-23	2-24	2-25	2-26	2-27	2-28	2-29	2-30	3-01	3-02	3-03	3-04	3-05	3-06	3-07	3-08	3-09	3-10	3-11	3-12	3-13	3-14	3-15	3-16	3-17	3-18	3-19	3-20	3-21	3-22	3-23	3-24	3-25	3-26	3-27	3-28	3-29	3-30	3-31	4-01	4-02	4-03	4-04	4-05	4-06	4-07	4-08	4-09	4-10	4-11	4-12	4-13	4-14	4-15	4-16	4-17	4-18	4-19	4-20	4-21	4-22	4-23	4-24	4-25	4-26	4-27	4-28	4-29	4-30	5-01	5-02	5-03	5-04	5-05	5-06	5-07	5-08	5-09	5-10	5-11	5-12	5-13	5-14	5-15	5-16	5-17	5-18	5-19	5-20	5-21	5-22	5-23	5-24	5-25	5-26	5-27	5-28	5-29	5-30	5-31	6-01	6-02	6-03	6-04	6-05	6-06	6-07	6-08	6-09	6-10	6-11	6-12	6-13	6-14	6-15	6-16	6-17	6-18	6-19	6-20	6-21	6-22	6-23	6-24	6-25	6-26	6-27	6-28	6-29	6-30	7-01	7-02	7-03	7-04	7-05	7-06	7-07	7-08	7-09	7-10	7-11	7-12	7-13	7-14	7-15	7-16	7-17	7-18	7-19	7-20	7-21	7-22	7-23	7-24	7-25	7-26	7-27	7-28	7-29	7-30	7-31	8-01	8-02	8-03	8-04	8-05	8-06	8-07	8-08	8-09	8-10	8-11	8-12	8-13	8-14	8-15	8-16	8-17	8-18	8-19	8-20	8-21	8-22	8-23	8-24	8-25	8-26	8-27	8-28	8-29	8-30	8-31	9-01	9-02	9-03	9-04	9-05	9-06	9-07	9-08	9-09	9-10	9-11	9-12	9-13	9-14	9-15	9-16	9-17	9-18	9-19	9-20	9-21	9-22	9-23	9-24	9-25	9-26	9-27	9-28	9-29	9-30	10-01	10-02	10-03	10-04	10-05	10-06	10-07	10-08	10-09	10-10	10-11	10-12	10-13	10-14	10-15	10-16	10-17	10-18	10-19	10-20	10-21	10-22	10-23	10-24	10-25	10-26	10-27	10-28	10-29	10-30	10-31	11-01	11-02	11-03	11-04	11-05	11-06	11-07	11-08	11-09	11-10	11-11	11-12	11-13	11-14	11-15	11-16	11-17	11-18	11-19	11-20	11-21	11-22	11-23	11-24
--	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

STATION 3, PLAIN 1, R110 4

[illegible]

[illegible]

OUTFLOWS FROM MANAQUE RESERVOIR

ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1	0	ISPA2	0	ISPA3	0	ISPA4	0
ISPAO	ICOMP	TECON	0	ISPA6	0	ISPA1							

HYDROGRAPH AT STA 5 FOR PLAN 1, R101.4

0.	10.	20.	30.	40.	50.	60.	70.	80.
0.	100.	110.	120.	130.	140.	150.	160.	170.
90.	200.	210.	220.	230.	240.	250.	260.	270.
180.	300.	310.	320.	330.	340.	350.	360.	370.
270.	400.	410.	420.	430.	440.	450.	460.	470.
360.	500.	510.	520.	530.	540.	550.	560.	570.
450.	600.	610.	620.	630.	640.	650.	660.	670.
540.	700.	710.	720.	730.	740.	750.	760.	770.
630.	800.	810.	820.	830.	840.	850.	860.	870.
720.	900.	910.	920.	930.	940.	950.	960.	970.
810.	1000.	1010.	1020.	1030.	1040.	1050.	1060.	1070.
900.	1100.	1110.	1120.	1130.	1140.	1150.	1160.	1170.
990.	1200.	1210.	1220.	1230.	1240.	1250.	1260.	1270.
1080.	1300.	1310.	1320.	1330.	1340.	1350.	1360.	1370.
1170.	1400.	1410.	1420.	1430.	1440.	1450.	1460.	1470.
1260.	1500.	1510.	1520.	1530.	1540.	1550.	1560.	1570.
1350.	1600.	1610.	1620.	1630.	1640.	1650.	1660.	1670.
1440.	1700.	1710.	1720.	1730.	1740.	1750.	1760.	1770.
1530.	1800.	1810.	1820.	1830.	1840.	1850.	1860.	1870.
1620.	1900.	1910.	1920.	1930.	1940.	1950.	1960.	1970.
1710.	2000.	2010.	2020.	2030.	2040.	2050.	2060.	2070.
1800.	2100.	2110.	2120.	2130.	2140.	2150.	2160.	2170.
1890.	2200.	2210.	2220.	2230.	2240.	2250.	2260.	2270.
1980.	2300.	2310.	2320.	2330.	2340.	2350.	2360.	2370.
2070.	2400.	2410.	2420.	2430.	2440.	2450.	2460.	2470.
2160.	2500.	2510.	2520.	2530.	2540.	2550.	2560.	2570.
2250.	2600.	2610.	2620.	2630.	2640.	2650.	2660.	2670.
2340.	2700.	2710.	2720.	2730.	2740.	2750.	2760.	2770.
2430.	2800.	2810.	2820.	2830.	2840.	2850.	2860.	2870.
2520.	2900.	2910.	2920.	2930.	2940.	2950.	2960.	2970.
2610.	3000.	3010.	3020.	3030.	3040.	3050.	3060.	3070.
2700.	3100.	3110.	3120.	3130.	3140.	3150.	3160.	3170.
2790.	3200.	3210.	3220.	3230.	3240.	3250.	3260.	3270.
2880.	3300.	3310.	3320.	3330.	3340.	3350.	3360.	3370.
2970.	3400.	3410.	3420.	3430.	3440.	3450.	3460.	3470.
3060.	3500.	3510.	3520.	3530.	3540.	3550.	3560.	3570.
3150.	3600.	3610.	3620.	3630.	3640.	3650.	3660.	3670.
3240.	3700.	3710.	3720.	3730.	3740.	3750.	3760.	3770.
3330.	3800.	3810.	3820.	3830.	3840.	3850.	3860.	3870.
3420.	3900.	3910.	3920.	3930.	3940.	3950.	3960.	3970.
3510.	4000.	4010.	4020.	4030.	4040.	4050.	4060.	4070.
3600.	4100.	4110.	4120.	4130.	4140.	4150.	4160.	4170.
3690.	4200.	4210.	4220.	4230.	4240.	4250.	4260.	4270.
3780.	4300.	4310.	4320.	4330.	4340.	4350.	4360.	4370.
3870.	4400.	4410.	4420.	4430.	4440.	4450.	4460.	4470.
3960.	4500.	4510.	4520.	4530.	4540.	4550.	4560.	4570.
4050.	4600.	4610.	4620.	4630.	4640.	4650.	4660.	4670.
4140.	4700.	4710.	4720.	4730.	4740.	4750.	4760.	4770.
4230.	4800.	4810.	4820.	4830.	4840.	4850.	4860.	4870.
4320.	4900.	4910.	4920.	4930.	4940.	4950.	4960.	4970.
4410.	5000.	5010.	5020.	5030.	5040.	5050.	5060.	5070.
4500.	5100.	5110.	5120.	5130.	5140.	5150.	5160.	5170.
4590.	5200.	5210.	5220.	5230.	5240.	5250.	5260.	5270.
4680.	5300.	5310.	5320.	5330.	5340.	5350.	5360.	5370.
4770.	5400.	5410.	5420.	5430.	5440.	5450.	5460.	5470.
4860.	5500.	5510.	5520.	5530.	5540.	5550.	5560.	5570.
4950.	5600.	5610.	5620.	5630.	5640.	5650.	5660.	5670.
5040.	5700.	5710.	5720.	5730.	5740.	5750.	5760.	5770.
5130.	5800.	5810.	5820.	5830.	5840.	5850.	5860.	5870.
5220.	5900.	5910.	5920.	5930.	5940.	5950.	5960.	5970.
5310.	6000.	6010.	6020.	6030.	6040.	6050.	6060.	6070.
5400.	6100.	6110.	6120.	6130.	6140.	6150.	6160.	6170.
5490.	6200.	6210.	6220.	6230.	6240.	6250.	6260.	6270.
5580.	6300.	6310.	6320.	6330.	6340.	6350.	6360.	6370.
5670.	6400.	6410.	6420.	6430.	6440.	6450.	6460.	6470.
5760.	6500.	6510.	6520.	6530.	6540.	6550.	6560.	6570.
5850.	6600.	6610.	6620.	6630.	6640.	6650.	6660.	6670.
5940.	6700.	6710.	6720.	6730.	6740.	6750.	6760.	6770.
6030.	6800.	6810.	6820.	6830.	6840.	6850.	6860.	6870.
6120.	6900.	6910.	6920.	6930.	6940.	6950.	6960.	6970.
6210.	7000.	7010.	7020.	7030.	7040.	7050.	7060.	7070.
6300.	7100.	7110.	7120.	7130.	7140.	7150.	7160.	7170.
6390.	7200.	7210.	7220.	7230.	7240.	7250.	7260.	7270.
6480.	7300.	7310.	7320.	7330.	7340.	7350.	7360.	7370.
6570.	7400.	7410.	7420.	7430.	7440.	7450.	7460.	7470.
6660.	7500.	7510.	7520.	7530.	7540.	7550.	7560.	7570.
6750.	7600.	7610.	7620.	7630.	7640.	7650.	7660.	7670.
6840.	7700.	7710.	7720.	7730.	7740.	7750.	7760.	7770.
6930.	7800.	7810.	7820.	7830.	7840.	7850.	7860.	7870.
7020.	7900.	7910.	7920.	7930.	7940.	7950.	7960.	7970.
7110.	8000.	8010.	8020.	8030.	8040.	8050.	8060.	8070.
7200.	8100.	8110.	8120.	8130.	8140.	8150.	8160.	8170.
7290.	8200.	8210.	8220.	8230.	8240.	8250.	8260.	8270.
7380.	8300.	8310.	8320.	8330.	8340.	8350.	8360.	8370.
7470.	8400.	8410.	8420.	8430.	8440.	8450.	8460.	8470.
7560.	8500.	8510.	8520.	8530.	8540.	8550.	8560.	8570.
7650.	8600.	8610.	8620.	8630.	8640.	8650.	8660.	8670.
7740.	8700.	8710.	8720.	8730.	8740.	8750.	8760.	8770.
7830.	8800.	8810.	8820.	8830.	8840.	8850.	8860.	8870.
7920.	8900.	8910.	8920.	8930.	8940.	8950.	8960.	8970.
8010.	9000.	9010.	9020.	9030.	9040.	9050.	9060.	9070.
8100.	9100.	9110.	9120.	9130.	9140.	9150.	9160.	9170.
8190.	9200.	9210.	9220.	9230.	9240.	9250.	9260.	9270.
8280.	9300.	9310.	9320.	9330.	9340.	9350.	9360.	9370.
8370.	9400.	9410.	9420.	9430.	9440.	9450.	9460.	9470.
8460.	9500.	9510.	9520.	9530.	9540.	9550.	9560.	9570.
8550.	9600.	9610.	9620.	9630.	9640.	9650.	9660.	9670.
8640.	9700.	9710.	9720.	9730.	9740.	9750.	9760.	9770.
8730.	9800.	9810.	9820.	9830.	9840.	9850.	9860.	9870.
8820.	9900.	9910.	9920.	9930.	9940.	9950.	9960.	9970.
8910.	10000.	10010.	10020.	10030.	10040.	10050.	10060.	10070.
9000.	10100.	10110.	10120.	10130.	10140.	10150.	10160.	10170.
9090.	10200.	10210.	10220.	10230.	10240.	10250.	10260.	10270.
9180.	10300.	10310.	10320.	10330.	10340.	10350.	10360.	10370.
9270.	10400.	10410.	10420.	10430.	10440.	10450.	10460.	10470.
9360.	10500.	10510.	10520.	10530.	10540.	10550.	10560.	10570.
9450.	10600.	10610.	10620.	10630.	10640.	10650.	10660.	10670.
9540.	10700.	10710.	10720.	10730.	10740.	10750.	10760.	10770.
9630.	10800.	10810.	10820.	10830.	10840.	10850.	10860.	10870.
9720.	10900.	10910.	10920.	10930.	10940.	10950.	10960.	10970.
9810.	11000.	11010.	11020.	11030.	11040.	11050.	11060.	11070.
9900.	11100.	11110.	11120.	11130.	11140.	11150.	11160.	11170.
9990.	11200.	11210.	11220.	11230.	11240.	11250.	11260.	11270.
10080.	11300.	11310.	11320.	11330.	11340.	11350.	11360.	11370.
10170.	11400.	11410.	11420.	11430.	11440.	11450.	11460.	11470.
10260.	11500.	11510.	11520.	11530.	11540.	11550.	11560.	11570.
10350.	11600.	11610.	11620.	11630.	11640.	11650.	11660.	11670.
10440.	11700.	11710.	11720.	11730.	11740.	11750.	11760.	11770.
10530.	11800.	11810.	11820.	11830.	11840.	11850.	11860.	11870.
10620.	11900.	11910.	11920.	11930.	11940.	11950.	11960.	11970.
10710.	12000.	12010.	12020.	12030.	12040.	12050.	12060.	12070.
10800.	12100.	12110.	12120.	12130.	12140.	12150.	12160.	12170.
10890.	12200.	12210.	12220.	12230.	12240.	12250.	12260.	12270.
10980.	12300.	12310.	12320.	12330.	12340.	12350.	12360.	12370.
11070.	12400.	12410.	12420.	12430.	12440.	12450.	12460.	12470.
11160.	12500.	12510.	12520.	12530.	12540.	12550.	12560.	12570.
11250.	12600.	12610.	12620.	12630.	12640.	12650.	12660.	12670.
11340.	12700.	12710.	12720.	12730.	12740.	12750.	12760.	12770.
11430.	12800.	12810.	12820.	12830.	12840.	12850.	12860.	12870.
11520.	12900.	12910.	12920.	12930.	12940.	12950.	12960.	12970.
11610.	13000.	13010.	13020.	13030.	13040.	13050.	13060.	13070.
11700.	13100.	13110.	13120.	13130.	13140.	13150.	13160.	13170.
11790.	13200.	13210.	13220.	13230.	13240.	13250.	13260.	13270.
11880.	13300.	13310.	13320.	13330.	13340.	13350.	13360.	13370.
11970.	13400.	13410.	13420.	13430.	13440.	13450.	13460.	13470.
12060.	13500.	13510.	13520.	13530.	13540.	13550.	13560.	13570.
12150.	13600.	13610.	13620.	13630.	13640.	13650.	13660.	13670.
12240.	13700.	13710.	13720.	13730.	13740.	13750.	13760.	13770.
12330.	13800.	13810.	13820.	13830.	138			

AD-A069 943


NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. LAKE INEZ DAM (NJ-00228), PASSAIC --ETC(U)
MAY 79 R J JENNY

DACW61-78-C-0124

UNCLASSIFIED

NL

2 OF 2
AD
A069943



END
DATE
FILMED

7 79
DDC

CONOMI HYDROGRAPHY

[illegible]

SUM OF 2 HYDROGRAPHS AT		6 PLAN 1		8110 4		80	
0.	30.	10.	10.	10.	10.	10.	10.
107.	110.	130.	130.	130.	130.	130.	130.
106.	110.	130.	130.	130.	130.	130.	130.
105.	110.	130.	130.	130.	130.	130.	130.
104.	110.	130.	130.	130.	130.	130.	130.
103.	110.	130.	130.	130.	130.	130.	130.
102.	110.	130.	130.	130.	130.	130.	130.
101.	110.	130.	130.	130.	130.	130.	130.
100.	110.	130.	130.	130.	130.	130.	130.
99.	110.	130.	130.	130.	130.	130.	130.
98.	110.	130.	130.	130.	130.	130.	130.
97.	110.	130.	130.	130.	130.	130.	130.
96.	110.	130.	130.	130.	130.	130.	130.
95.	110.	130.	130.	130.	130.	130.	130.
94.	110.	130.	130.	130.	130.	130.	130.
93.	110.	130.	130.	130.	130.	130.	130.
92.	110.	130.	130.	130.	130.	130.	130.
91.	110.	130.	130.	130.	130.	130.	130.
90.	110.	130.	130.	130.	130.	130.	130.
89.	110.	130.	130.	130.	130.	130.	130.
88.	110.	130.	130.	130.	130.	130.	130.
87.	110.	130.	130.	130.	130.	130.	130.
86.	110.	130.	130.	130.	130.	130.	130.
85.	110.	130.	130.	130.	130.	130.	130.
84.	110.	130.	130.	130.	130.	130.	130.
83.	110.	130.	130.	130.	130.	130.	130.
82.	110.	130.	130.	130.	130.	130.	130.
81.	110.	130.	130.	130.	130.	130.	130.
80.	110.	130.	130.	130.	130.	130.	130.
79.	110.	130.	130.	130.	130.	130.	130.
78.	110.	130.	130.	130.	130.	130.	130.
77.	110.	130.	130.	130.	130.	130.	130.
76.	110.	130.	130.	130.	130.	130.	130.
75.	110.	130.	130.	130.	130.	130.	130.
74.	110.	130.	130.	130.	130.	130.	130.
73.	110.	130.	130.	130.	130.	130.	130.
72.	110.	130.	130.	130.	130.	130.	130.
71.	110.	130.	130.	130.	130.	130.	130.
70.	110.	130.	130.	130.	130.	130.	130.
69.	110.	130.	130.	130.	130.	130.	130.
68.	110.	130.	130.	130.	130.	130.	130.
67.	110.	130.	130.	130.	130.	130.	130.
66.	110.	130.	130.	130.	130.	130.	130.
65.	110.	130.	130.	130.	130.	130.	130.
64.	110.	130.	130.	130.	130.	130.	130.
63.	110.	130.	130.	130.	130.	130.	130.
62.	110.	130.	130.	130.	130.	130.	130.
61.	110.	130.	130.	130.	130.	130.	130.
60.	110.	130.	130.	130.	130.	130.	130.
59.	110.	130.	130.	130.	130.	130.	130.
58.	110.	130.	130.	130.	130.	130.	130.
57.	110.	130.	130.	130.	130.	130.	130.
56.	110.	130.	130.	130.	130.	130.	130.
55.	110.	130.	130.	130.	130.	130.	130.
54.	110.	130.	130.	130.	130.	130.	130.
53.	110.	130.	130.	130.	130.	130.	130.
52.	110.	130.	130.	130.	130.	130.	130.
51.	110.	130.	130.	130.	130.	130.	130.
50.	110.	130.	130.	130.	130.	130.	130.
49.	110.	130.	130.	130.	130.	130.	130.
48.	110.	130.	130.	130.	130.	130.	130.
47.	110.	130.	130.	130.	130.	130.	130.
46.	110.	130.	130.	130.	130.	130.	130.
45.	110.	130.	130.	130.	130.	130.	130.
44.	110.	130.	130.	130.	130.	130.	130.
43.	110.	130.	130.	130.	130.	130.	130.
42.	110.	130.	130.	130.	130.	130.	130.
41.	110.	130.	130.	130.	130.	130.	130.
40.	110.	130.	130.	130.	130.	130.	130.
39.	110.	130.	130.	130.	130.	130.	130.
38.	110.	130.	130.	130.	130.	130.	130.
37.	110.	130.	130.	130.	130.	130.	130.
36.	110.	130.	130.	130.	130.	130.	130.
35.	110.	130.	130.	130.	130.	130.	130.
34.	110.	130.	130.	130.	130.	130.	130.
33.	110.	130.	130.	130.	130.	130.	130.
32.	110.	130.	130.	130.	130.	130.	130.
31.	110.	130.	130.	130.	130.	130.	130.
30.	110.	130.	130.	130.	130.	130.	130.
29.	110.	130.	130.	130.	130.	130.	130.
28.	110.	130.	130.	130.	130.	130.	130.
27.	110.	130.	130.	130.	130.	130.	130.
26.	110.	130.	130.	130.	130.	130.	130.
25.	110.	130.	130.	130.	130.	130.	130.
24.	110.	130.	130.	130.	130.	130.	130.
23.	110.	130.	130.	130.	130.	130.	130.
22.	110.	130.	130.	130.	130.	130.	130.
21.	110.	130.	130.	130.	130.	130.	130.
20.	110.	130.	130.	130.	130.	130.	130.
19.	110.	130.	130.	130.	130.	130.	130.
18.	110.	130.	130.	130.	130.	130.	130.
17.	110.	130.	130.	130.	130.	130.	130.
16.	110.	130.	130.	130.	130.	130.	130.
15.	110.	130.	130.	130.	130.	130.	130.
14.	110.	130.	130.	130.	130.	130.	130.
13.	110.	130.	130.	130.	130.	130.	130.
12.	110.	130.	130.	130.	130.	130.	130.
11.	110.	130.	130.	130.	130.	130.	130.
10.	110.	130.	130.	130.	130.	130.	130.
9.	110.	130.	130.	130.	130.	130.	130.
8.	110.	130.	130.	130.	130.	130.	130.
7.	110.	130.	130.	130.	130.	130.	130.
6.	110.	130.	130.	130.	130.	130.	130.
5.	110.	130.	130.	130.	130.	130.	130.
4.	110.	130.	130.	130.	130.	130.	130.
3.	110.	130.	130.	130.	130.	130.	130.
2.	110.	130.	130.	130.	130.	130.	130.
1.	110.	130.	130.	130.	130.	130.	130.
0.	110.	130.	130.	130.	130.	130.	130.

HYDROGRAPH ROUTING

ROUTING CHANNEL OUTFLOWS TO STATION 7 AT LAKE INEZ

ISFAD	SCMP	SECON	ITAPE	JPLT	JPRF	ISMAE	ISTAGE	IAUTO
7	1	0	ROUTING DATA	0	0	1	0	0
CLS5	CLOS	AVG	INIS	ISAC	ISPT	ISMP	LSTR	0
0.0	0.000	0.00	1	1	0	0	0	0
MS75	MS70L	LAC	ANSHK	2	TKM	STOMA	ISPRAT	0
1	0	0	0.000	0.000	0.000	0.	0.	0

CHANNEL DEPTH CHANNEL ROUTING

QMI1	QMI2	QMI3	ELWIT	ELMAZ	ELSTM	SEL
1000	1455	1000	203.0	240.0	0400.	00200

CROSS SECTION COORDINATES--STA=ELEV--STA=ELEV--ETC
 0+00 243.00 1009.30 220.10 1150.00 207.00 1150.00 203.00
 1225.00 237.00 1275.70 220.10 1600.00 240.00

STORAGE	0.00	24.04	57.47	91.00	137.13	194.10	262.69	342.73	434.29	536.40
	076.06	456.94	1679.36	1343.05	1650.47	1949.21	2396.07	2823.03	3298.12	3815.31
OUTFLOW	0.00	374.07	1002.47	1983.42	3289.15	4944.69	6982.14	9420.67	12460.43	15417.00
	10445.05	23251.37	26614.76	35082.79	42040.85	51591.05	61084.59	71657.14	83005.08	102023.01
STAGE	203.00	204.95	206.49	208.44	210.79	212.74	214.68	216.43	218.26	220.23
	222.47	224.42	226.37	228.32	230.26	232.21	234.16	236.11	238.05	240.00
FLOW	0.00	326.07	1402.47	1983.42	3289.15	4944.69	6982.14	9420.67	12460.43	15417.00
	18665.05	23751.37	26614.76	35082.79	42040.85	51591.05	61084.59	71657.14	83005.08	102023.01

STATION

SUFFRAGE									
0.	0.	2.	7.	10.	21.	31.	40.	49.	50.
100	170	100	93	150	112	110	130	140	150
105	175	105	98	155	117	115	135	145	155
110	180	110	103	160	122	120	140	150	160
115	185	115	108	165	127	125	145	155	165
120	190	120	113	170	132	130	150	160	170
125	195	125	118	175	137	135	155	165	175
130	200	130	123	180	142	140	160	170	180
135	205	135	128	185	147	145	165	175	185
140	210	140	133	190	152	150	170	180	190
145	215	145	138	195	157	155	175	185	195
150	220	150	143	200	162	160	180	190	200
155	225	155	148	205	167	165	185	195	205
160	230	160	153	210	172	170	190	200	210
165	235	165	158	215	177	175	195	205	215
170	240	170	163	220	182	180	200	210	220
175	245	175	168	225	187	185	205	215	225
180	250	180	173	230	192	190	210	220	230
185	255	185	178	235	197	195	215	225	235
190	260	190	183	240	202	200	220	230	240
195	265	195	188	245	207	205	225	235	245
200	270	200	193	250	212	210	230	240	250
205	275	205	198	255	217	215	235	245	255
210	280	210	203	260	222	220	240	250	260
215	285	215	208	265	227	225	245	255	265
220	290	220	213	270	232	230	250	260	270
225	295	225	218	275	237	235	255	265	275
230	300	230	223	280	242	240	260	270	280
235	305	235	228	285	247	245	265	275	285
240	310	240	233	290	252	250	270	280	290
245	315	245	238	295	257	255	275	285	295
250	320	250	243	300	262	260	280	290	300
255	325	255	248	305	267	265	285	295	305
260	330	260	253	310	272	270	290	300	310
265	335	265	258	315	277	275	295	305	315
270	340	270	263	320	282	280	300	310	320
275	345	275	268	325	287	285	305	315	325
280	350	280	273	330	292	290	310	320	330
285	355	285	278	335	297	295	315	325	335
290	360	290	283	340	302	300	320	330	340
295	365	295	288	345	307	305	325	335	345
300	370	300	293	350	312	310	330	340	350
305	375	305	298	355	317	315	335	345	355
310	380	310	303	360	322	320	340	350	360
315	385	315	308	365	327	325	345	355	365
320	390	320	313	370	332	330	350	360	370
325	395	325	318	375	337	335	355	365	375
330	400	330	323	380	342	340	360	370	380
335	405	335	328	385	347	345	365	375	385
340	410	340	333	390	352	350	370	380	390
345	415	345	338	395	357	355	375	385	395
350	420	350	343	400	362	360	380	390	400
355	425	355	348	405	367	365	385	395	405
360	430	360	353	410	372	370	390	400	410
365	435	365	358	415	377	375	395	405	415
370	440	370	363	420	382	380	400	410	420
375	445	375	368	425	387	385	405	415	425
380	450	380	373	430	392	390	410	420	430
385	455	385	378	435	397	395	415	425	435
390	460	390	383	440	402	400	420	430	440
395	465	395	388	445	407	405	425	435	445
400	470	400	393	450	412	410	430	440	450
405	475	405	398	455	417	415	435	445	455
410	480	410	403	460	422	420	440	450	460
415	485	415	408	465	427	425	445	455	465
420	490	420	413	470	432	430	450	460	470
425	495	425	418	475	437	435	455	465	475
430	500	430	423	480	442	440	460	470	480
435	505	435	428	485	447	445	465	475	485
440	510	440	433	490	452	450	470	480	490
445	515	445	438	495	457	455	475	485	495
450	520	450	443	500	462	460	480	490	500
455	525	455	448	505	467	465	485	495	505
460	530	460	453	510	472	470	490	500	510
465	535	465	458	515	477	475	495	505	515
470	540	470	463	520	482	480	500	510	520
475	545	475	468	525	487	485	505	515	525
480	550	480	473	530	492	490	510	520	530
485	555	485	478	535	497	495	515	525	535
490	560	490	483	540	502	500	520	530	540
495	565	495	488	545	507	505	525	535	545
500	570	500	493	550	512	510	530	540	550
505	575	505	498	555	517	515	535	545	555
510	580	510	503	560	522	520	540	550	560
515	585	515	508	565	527	525	545	555	565
520	590	520	513	570	532	530	550	560	570
525	595	525	518	575	537	535	555	565	575
530	600	530	523	580	542	540	560	570	580
535	605	535	528	585	547	545	565	575	585
540	610	540	533	590	552	550	570	580	590
545	615	545	538	595	557	555	575	585	595
550	620	550	543	600	562	560	580	590	600
555	625	555	548	605	567	565	585	595	605
560	630	560	553	610	572	570	590	600	610
565	635	565	558	615	577	575	595	605	615
570	640	570	563	620	582	580	600	610	620
575	645	575	568	625	587	585	605	615	625
580	650	580	573	630	592	590	610	620	630
585	655	585	578	635	597	595	615	625	635
590	660	590	583	640	602	600	620	630	640
595	665	595	588	645	607	605	625	635	645
600	670	600	593	650	612	610	630	640	650
605	675	605	598	655	617	615	635	645	655
610	680	610	603	660	622	620	640	650	660
615	685	615	608	665	627	625	645	655	665
620	690	620	613	670	632	630	650	660	670
625	695	625	618	675	637	635	655	665	675
630	700	630	623	680	642	640	660	670	680
635	705	635	628	685	647	645	665	675	685
640	710	640	633	690	652	650	670	680	690
645	715	645	638	695	657	655	675	685	695
650	720	650	643	700	662	660	680	690	700
655	725	655	648	705	667	665	685	695	705
660	730	660	653	710	672	670	690	700	710
665	735	665	658	715	677	675	695	705	715
670	740	670	663	720	682	680	700	710	720
675	745	675	668	725	687	685	705	715	725
680	750	680	673	730	692	690	710	720	730
685	755	685	678	735	697	695	715	725	735
690	760	690	683	740	702	700	720	730	740
695	765	695	688	745	707	705	725	735	745
700	770	700	693	750	712	710	730	740	750
705	775	705	698	755	717	715	735	745	755
710	780	710	703	760	722	720	740	750	760
715	785	715	708	765	727	725	745	755	765
720	790	720	713	770	732	730	750	760	770
725	795	725	718	775	737	735	755	765	775
730	800	730	723	780	742	740	760	770	780
735	805	735	728	785	747	745	765	775	785
740	810	740	733	790	752	750	770	780	790
745	815	745	738	795	757	755	775	785	795
750	820	750	743	800	762	760	780	790	800
755	825	755	748	805	767	765	785	795	805
760	830	760	753	810	772	770	790	800	810
765	835	765	758	815	777	775	795	805	815
770	840	770	763	820	782	780	800	810	820
775	845	775	768	825	787	785	805	815	825
780	850	780	773	830	792	790	810	820	830
785	855	785	778	835	797	795	815	825	835
790	860	790	783	840	802	800	820	830	840
795	865	795	788	845	807	805	825	835	845
800	870	800	793	850	812	810	830	840	850
805	875	805	798	855	817	815	835	845	855
810	880	810	803	860	822	820	840	850	860
815	885	815	808	865	827	825	845	855	865
820	890	820	813	870	832	830	850	860	870
825	895	825	818	875	837	835	855	865	875
830	900	830	823						

0.	0.	0.	0.	1.	2.	3.	4.	5.
0.	0.	0.	0.	10.	10.	11.	12.	13.
1.	1.	1.	1.	10.	10.	11.	12.	13.
2.	2.	2.	2.	10.	10.	11.	12.	13.
3.	3.	3.	3.	10.	10.	11.	12.	13.
4.	4.	4.	4.	10.	10.	11.	12.	13.
5.	5.	5.	5.	10.	10.	11.	12.	13.
6.	6.	6.	6.	10.	10.	11.	12.	13.
7.	7.	7.	7.	10.	10.	11.	12.	13.
8.	8.	8.	8.	10.	10.	11.	12.	13.
9.	9.	9.	9.	10.	10.	11.	12.	13.
10.	10.	10.	10.	10.	10.	11.	12.	13.
11.	11.	11.	11.	10.	10.	11.	12.	13.
12.	12.	12.	12.	10.	10.	11.	12.	13.
13.	13.	13.	13.	10.	10.	11.	12.	13.
14.	14.	14.	14.	10.	10.	11.	12.	13.
15.	15.	15.	15.	10.	10.	11.	12.	13.
16.	16.	16.	16.	10.	10.	11.	12.	13.
17.	17.	17.	17.	10.	10.	11.	12.	13.
18.	18.	18.	18.	10.	10.	11.	12.	13.
19.	19.	19.	19.	10.	10.	11.	12.	13.
20.	20.	20.	20.	10.	10.	11.	12.	13.
21.	21.	21.	21.	10.	10.	11.	12.	13.
22.	22.	22.	22.	10.	10.	11.	12.	13.
23.	23.	23.	23.	10.	10.	11.	12.	13.
24.	24.	24.	24.	10.	10.	11.	12.	13.
25.	25.	25.	25.	10.	10.	11.	12.	13.
26.	26.	26.	26.	10.	10.	11.	12.	13.
27.	27.	27.	27.	10.	10.	11.	12.	13.
28.	28.	28.	28.	10.	10.	11.	12.	13.
29.	29.	29.	29.	10.	10.	11.	12.	13.
30.	30.	30.	30.	10.	10.	11.	12.	13.
31.	31.	31.	31.	10.	10.	11.	12.	13.
32.	32.	32.	32.	10.	10.	11.	12.	13.
33.	33.	33.	33.	10.	10.	11.	12.	13.
34.	34.	34.	34.	10.	10.	11.	12.	13.
35.	35.	35.	35.	10.	10.	11.	12.	13.
36.	36.	36.	36.	10.	10.	11.	12.	13.
37.	37.	37.	37.	10.	10.	11.	12.	13.
38.	38.	38.	38.	10.	10.	11.	12.	13.
39.	39.	39.	39.	10.	10.	11.	12.	13.
40.	40.	40.	40.	10.	10.	11.	12.	13.
41.	41.	41.	41.	10.	10.	11.	12.	13.
42.	42.	42.	42.	10.	10.	11.	12.	13.
43.	43.	43.	43.	10.	10.	11.	12.	13.
44.	44.	44.	44.	10.	10.	11.	12.	13.
45.	45.	45.	45.	10.	10.	11.	12.	13.
46.	46.	46.	46.	10.	10.	11.	12.	13.
47.	47.	47.	47.	10.	10.	11.	12.	13.
48.	48.	48.	48.	10.	10.	11.	12.	13.
49.	49.	49.	49.	10.	10.	11.	12.	13.
50.	50.	50.	50.	10.	10.	11.	12.	13.
51.	51.	51.	51.	10.	10.	11.	12.	13.
52.	52.	52.	52.	10.	10.	11.	12.	13.
53.	53.	53.	53.	10.	10.	11.	12.	13.
54.	54.	54.	54.	10.	10.	11.	12.	13.
55.	55.	55.	55.	10.	10.	11.	12.	13.
56.	56.	56.	56.	10.	10.	11.	12.	13.
57.	57.	57.	57.	10.	10.	11.	12.	13.
58.	58.	58.	58.	10.	10.	11.	12.	13.
59.	59.	59.	59.	10.	10.	11.	12.	13.

[illegible]

MAXIMUM STORAGE - 1043.

SI 0015 226.2

ISSTA0	IComp	IRecon	ITape	JPLY	JOST	LNAME	ISTAGE	IAUTO
--------	-------	--------	-------	------	------	-------	--------	-------

ESTAB		ECOMP	ECOM	STAGE	JOLT	JOOT	EMARK	STAGE	EMARK
9	2	0	0	0	0	0	1	0	0
40	16	17	23	34	43	52			
71	91	110	129	130	140	150			
190	460	239	219	239	239	235			
661	624	799	917	949	907	764			
566	510	592	683	679	681	682			
570	625	777	852	874	909	1003			
1397	1508	1622	2066	2280	2537	2891			
4203	4930	5927	7406	9741	12693	15449			
28893	30003	29031	29657	29191	29692	29593			
27794	28131	28253	28173	28455	28413	28091			
28336	28513	28594	28556	28653	28363	28241			
27177	26816	26637	26052	25653	25210	24763			
23500	23111	22782	22364	21962	21561	20246			
17933	16926	16519	16156	15760	15452	14762			
15516	15143	14794	14493	14192	13871	13713			
12715	12456	12211	11956	11727	11531	11341			
10493	10260	9996	9671	9729	9617	9451			
8723	8573	8394	8231	8083	7953	7827			
7128	7051	6962	6882	6803	6733	6715			
6249	6176	6114	6051	5973	5894	5862			
5382	5292	5242	5191	5133	5061	4987			
4597	4543	4492	4442	4392	4342	4292			
4092	4042	3992	3942	3892	3842	3792			
3641	3571	3526	3471	3406	3340	3301			
3246	3176	3126	3066	3021	2956	2911			
2893	2876	2846	2821	2772	2735	2696			
2693	2626	2586	2541	2496	2471	2435			
2308	2296	2266	2241	2206	2171	2135			
2108	2096	2066	2041	2006	1971	1935			
1908	1896	1866	1841	1806	1771	1735			
1708	1696	1666	1641	1606	1571	1535			
1508	1496	1466	1441	1406	1371	1335			
1308	1296	1266	1241	1206	1171	1135			
1108	1096	1066	1041	1006	971	935			
908	896	866	841	806	771	735			
708	696	666	641	606	571	535			
508	496	466	441	406	371	335			
308	296	266	241	206	171	135			
108	96	66	41	6	0	0			

HYDROGRAPH ROUTING

01000

STATION 10, PLAN 1, RATIO 4

ITERATIVE SOLUTION DID NOT CONVERGE 89 1 0.000 2.000E+02 4.675E+02 2.000E+02 -7.342E+32

ITERATIVE SOLUTION DID NOT CONVERGE 119 1 0.000 2.000E+02 4.597E+02 2.000E+02 -7.356E+32

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW		STORAGE	
2.	3.	2.	3.
300.	300.	300.	300.
305.	305.	305.	305.
310.	310.	310.	310.
315.	315.	315.	315.
320.	320.	320.	320.
325.	325.	325.	325.
330.	330.	330.	330.
335.	335.	335.	335.
340.	340.	340.	340.
345.	345.	345.	345.
350.	350.	350.	350.
355.	355.	355.	355.
360.	360.	360.	360.
365.	365.	365.	365.
370.	370.	370.	370.
375.	375.	375.	375.
380.	380.	380.	380.
385.	385.	385.	385.
390.	390.	390.	390.
395.	395.	395.	395.
400.	400.	400.	400.
405.	405.	405.	405.
410.	410.	410.	410.
415.	415.	415.	415.
420.	420.	420.	420.
425.	425.	425.	425.
430.	430.	430.	430.
435.	435.	435.	435.
440.	440.	440.	440.
445.	445.	445.	445.
450.	450.	450.	450.
455.	455.	455.	455.
460.	460.	460.	460.
465.	465.	465.	465.
470.	470.	470.	470.
475.	475.	475.	475.
480.	480.	480.	480.
485.	485.	485.	485.
490.	490.	490.	490.
495.	495.	495.	495.
500.	500.	500.	500.
505.	505.	505.	505.
510.	510.	510.	510.
515.	515.	515.	515.
520.	520.	520.	520.
525.	525.	525.	525.
530.	530.	530.	530.
535.	535.	535.	535.
540.	540.	540.	540.
545.	545.	545.	545.
550.	550.	550.	550.
555.	555.	555.	555.
560.	560.	560.	560.
565.	565.	565.	565.
570.	570.	570.	570.
575.	575.	575.	575.
580.	580.	580.	580.
585.	585.	585.	585.
590.	590.	590.	590.
595.	595.	595.	595.
600.	600.	600.	600.
605.	605.	605.	605.
610.	610.	610.	610.
615.	615.	615.	615.
620.	620.	620.	620.
625.	625.	625.	625.
630.	630.	630.	630.
635.	635.	635.	635.
640.	640.	640.	640.
645.	645.	645.	645.
650.	650.	650.	650.
655.	655.	655.	655.
660.	660.	660.	660.
665.	665.	665.	665.
670.	670.	670.	670.
675.	675.	675.	675.
680.	680.	680.	680.
685.	685.	685.	685.
690.	690.	690.	690.
695.	695.	695.	695.
700.	700.	700.	700.
705.	705.	705.	705.
710.	710.	710.	710.
715.	715.	715.	715.
720.	720.	720.	720.
725.	725.	725.	725.
730.	730.	730.	730.
735.	735.	735.	735.
740.	740.	740.	740.
745.	745.	745.	745.
750.	750.	750.	750.
755.	755.	755.	755.
760.	760.	760.	760.
765.	765.	765.	765.
770.	770.	770.	770.
775.	775.	775.	775.
780.	780.	780.	780.
785.	785.	785.	785.
790.	790.	790.	790.
795.	795.	795.	795.
800.	800.	800.	800.
805.	805.	805.	805.
810.	810.	810.	810.
815.	815.	815.	815.
820.	820.	820.	820.
825.	825.	825.	825.
830.	830.	830.	830.
835.	835.	835.	835.
840.	840.	840.	840.
845.	845.	845.	845.
850.	850.	850.	850.
855.	855.	855.	855.
860.	860.	860.	860.
865.	865.	865.	865.
870.	870.	870.	870.
875.	875.	875.	875.
880.	880.	880.	880.
885.	885.	885.	885.
890.	890.	890.	890.
895.	895.	895.	895.
900.	900.	900.	900.
905.	905.	905.	905.
910.	910.	910.	910.
915.	915.	915.	915.
920.	920.	920.	920.
925.	925.	925.	925.
930.	930.	930.	930.
935.	935.	935.	935.
940.	940.	940.	940.
945.	945.	945.	945.
950.	950.	950.	950.
955.	955.	955.	955.
960.	960.	960.	960.
965.	965.	965.	965.
970.	970.	970.	970.
975.	975.	975.	975.
980.	980.	980.	980.
985.	985.	985.	985.
990.	990.	990.	990.
995.	995.	995.	995.
1000.	1000.	1000.	1000.

[illegible]

[illegible][illegible]

-----SIA-11EV-SIA-11EV--E13

[illegible]

11. PLAN 1. 2710 4

D-38

[illegible]

MAXIMUM STAGE IS 230.7

139.7

10

	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	2403	2404	2405	2406	2407	2408	2409	2410	2411	2412	2413	2414	2415	2416	2417	2418	2419	2420	2421	2422	2423	2424	2425	2426	2427	2428	2429	2430	2431	2432	2433	2434	2435	2436	2437	2438	2439	2440	2441	2442	2443	2444	2445	2446	2447	2
--	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	---

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE METERS)

OPERATION	STATION	AREA	PLAN RATIO	1	RATIO 2	RATIOS APPLIED TO FLOWS	
						RATIO 1	RATIO 2
						.50	1.00
HYDROGRAPH AT	1	2.90	1	100%	2031	5302	10403
	2	7.51	1	36.02%	75.00%	130.12%	300.25%
	3	2.90	1	100%	2031	5302	10403
	4	7.51	1	29.98%	74.85%	109.66%	209.65%
ROUTED TO	5	2.90	1	100%	2031	5302	10403
	6	7.51	1	29.98%	74.85%	109.66%	209.65%
	7	2.90	1	100%	2031	5302	10403
	8	7.51	1	29.98%	74.85%	109.66%	209.65%
HYDROGRAPH AT	9	0.00	1	2031	7075	11150	26300
	10	0.00	1	60.15%	200.15%	400.00%	801.37%
	11	2.90	1	2031	7075	11150	26300
	12	7.51	1	60.15%	200.15%	400.00%	801.37%
2 COMBINED	13	2.90	1	2031	7075	11150	26300
	14	7.51	1	60.15%	200.15%	400.00%	801.37%
	15	2.90	1	2031	7075	11150	26300
	16	7.51	1	60.15%	200.15%	400.00%	801.37%
HYDROGRAPH AT	17	2.90	1	2031	7075	11150	26300
	18	7.51	1	60.15%	200.15%	400.00%	801.37%
	19	2.90	1	2031	7075	11150	26300
	20	7.51	1	60.15%	200.15%	400.00%	801.37%
2 COMBINED	21	2.90	1	2031	7075	11150	26300
	22	7.51	1	60.15%	200.15%	400.00%	801.37%
	23	2.90	1	2031	7075	11150	26300
	24	7.51	1	60.15%	200.15%	400.00%	801.37%
ROUTED TO	25	2.90	1	2031	7075	11150	26300
	26	7.51	1	60.15%	200.15%	400.00%	801.37%
	27	2.90	1	2031	7075	11150	26300
	28	7.51	1	60.15%	200.15%	400.00%	801.37%
HYDROGRAPH AT	29	2.90	1	2031	7075	11150	26300
	30	7.51	1	60.15%	200.15%	400.00%	801.37%
	31	2.90	1	2031	7075	11150	26300
	32	7.51	1	60.15%	200.15%	400.00%	801.37%
2 COMBINED	33	2.90	1	2031	7075	11150	26300
	34	7.51	1	60.15%	200.15%	400.00%	801.37%
	35	2.90	1	2031	7075	11150	26300
	36	7.51	1	60.15%	200.15%	400.00%	801.37%

PLAN 1		STATION 2			TIME
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT			HOURS
.10	1059.	244.0			00.50
.25	2662.	246.2			00.50
.50	5205.	248.7			00.50
1.00	10502.	250.0			00.50

PLAN 1		STATION 3			TIME
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT			HOURS
.10	1030.	255.3			01.00
.25	2590.	257.3			01.00
.50	5172.	259.2			01.00
1.00	10300.	261.5			01.00

PLAN 1		STATION 4			TIME
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT			HOURS
.10	701.	220.5			01.50
.25	2662.	221.9			01.50
.50	5290.	223.3			01.50
1.00	8030.	225.1			01.50

PLAN 1		STATION 7			TIME
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT			HOURS
.10	2025.	210.1			02.50
.25	4691.	210.7			02.50
.50	9311.	210.7			02.50
1.00	20211.	220.2			02.50

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1						
ELEVATION STORAGE OUTFLOW	INITIAL VALUE 100.00 300. 0.	SPILLWAY CREST 100.00 300. 0.	TOP OF DAM 211.10 1000. 2000.			
RATIO OF PWR	MAXIMUM STORAGE B.F. ALLV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	100.00	900.	2001.	0.00	0.00	0.00
.25	200.00	1800.	4000.	0.00	0.00	0.00
.50	200.00	3600.	8000.	0.00	0.00	0.00
1.00	210.00	7200.	16000.	0.00	0.00	0.00

PLAN 1 STATION 11

RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
.10	2002.	102.1	03.00
.25	4004.	107.2	02.56
.50	8008.	103.0	02.50
1.00	16016.	207.7	02.50

PLAN 1 STATION 12

RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
.10	2000.	100.0	03.00
.25	4000.	105.0	02.56
.50	8000.	100.0	02.50
1.00	16000.	200.0	02.50

DAMS IN NEW JERSEY—REFERENCE DATA

Wanacus River

No. 23-89

Name of Owner _____ Address _____
 Name of Dam Lake Inez County Passaic Location 22-31-2-7-5 ☐
 CONSTRUCTION: Date _____ By whom _____
 Stream Wanacus River Tributary to Pompton River
 DRAINAGE BASIN: Area _____ sq. mi. Description _____
 Description of valley below dam Residential (Pompton Lakes)
 DAMAGE FROM FAILURE: Probable _____
 Previous (date) _____
 Purpose _____ Type Concrete Wall
 Foundation _____
 Length _____ ft. Max. height _____ ft. Max. width of top _____ ft.
 Upstream slope _____ Downstream slope _____ Volume _____ Cu. yds.
 SPILLWAY: Type _____ Length _____ ft.
 Depth below top of _____ ft. Capacity _____ c. f. s. per sq. mi.
 RESERVOIR: Capacity _____ mill. gals. Area _____ acres. Length _____ ft.
 Outlets _____
 Remarks _____

Sources of data U.S.G.S. Sheets, Continuous Profile Date Sept. 11, 1965
 PFB

Report on Dam Inspection

Dam No. 23-89

Lake Inez Dam

Wanaque River

Willard Kluge, Artistic Weaving Co., Owner

Borough of Pompton Lakes, Passaic Co.

Location 23-31-8-7-5

At the request of Councilman Dwinell Travers, Borough of Pompton Lakes, an inspection of the subject dam was made in his company on May 24, 1960. Also present at the inspection were Mr. Frank Magill of Pompton Lakes, and Steve Dola and James Riley of this office.

The Lake Inez dam which is located upstream of Wanaque Avenue and the main part of the Borough of Pompton Lakes, once supplied water and power for an old adjacent mill which is now being operated as a weaving plant. Basically the dam is of heavy masonry construction with a concrete apron downstream. The main spillway has a length of 205.9 feet with a free board of 2.6 feet above the spillway crest. The old raceway through the powerhouse of the old mill has been walled off. The only other opening is a small sluiceway with timber gates in a span of 9.4 feet.


In the writer's opinion, the over-all structural condition of the dam, with the exception of the timber sluice gate and portions of the easterly end of the dam, is sound.

The timber sluice gate, which is located at the westerly end of the dam, is in very poor condition and failure is only a matter of time. Failure of the gate would only de-water the lake and complete failure of the dam probably would be unlikely. However, failure of the gate in time of a major flood may aggravate flooding conditions downstream.

Portions of the top spillway have shifted out of position in the area directly adjacent to an old forebay at the easterly end of the dam. Indications are, however, that this condition has existed for quite some time. Several points of leakage through the masonry spillway section were also noted in this same area. Grouting with the lake level lowered would probably eliminate these conditions.

A water and sand boil was noted within the old forebay downstream of its upstream wall. Indications are that this condition has also existed for quite some time. Combination of grouting and the placement of a clay blanket directly upstream would probably eliminate this conditions. Filling in of the forebay would also help to eliminate this conditions.

It is recommended that the attached letter be sent to the owner of the Lake Inez dam.


Michael J. Galley
Supervising Engineer Hydraulic


Trenton, New Jersey
June 2, 1960

Note: Stream survey sheet showing details of dam is attached.

D-48

FROM THE OVERFLOW WEIR NJ00214










PLATE D-3

JENNY/HUDSON/157





1000 0 1000 2000 3000 4000 5000 6000
SCALE IN FEET




LAKE INEZ DAM

JENNY-LEEDSHILL

FEBRUARY 1979

PLATE D-2



SENIOR/LEADS TO JUL 1979




PLATE D-3
Submitted for review Feb. 1971

